



08/25/2016  
 P. O. Box 1196 - Carencro, LA 70520  
 4710 Cameron Street - Scott, LA 70583  
 Phone: 337-852-1105  
 Fax: 337-889-5495

BTEX												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">BT20</a>	60" x 4'	0		2006	11497			0	No	Yes	" / "	
<a href="#">BT19</a>	36" x 3.75'	0		0000	0			0	No	Yes	" / "	No tag on unit
<a href="#">BT26</a>	4" x 3'	ATMOS		2007	1001-612			0	No	Yes	" / "	BTEX Eliminator
<a href="#">BT22</a>	3.75" x 3'	0		0000	97571			0	No	Yes	" / "	Fins partially bent
<a href="#">BT12</a>	0	0		0000	97775			0	No	No	" / "	
<a href="#">BT17</a>	0	0		2010	1001-1266			0	No	Yes	" / "	
<a href="#">BT28</a>	0" x 11.25' x 5'10"	5		2004	H8F73601-03			0	No	Yes	" / "	
<a href="#">BT29</a>	0" x 6' x 5'10"	5		2004	EL8E77701-03			0	No	Yes	" / "	
<a href="#">BT30</a>	0" x 6.5'	0		0	0				No	No	" / "	5'7" W x 6'6"lg x 13'9"T
<a href="#">BT31P</a>	0	0		0	0						" / "	BTEX for R227P

Towers												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">T293P</a>	96" x 27.5'	1400		1973	73-8244			0	Yes	No	" / "	
<a href="#">T302P</a>	96" x 25'	1000		1995	0			0	No	No	" / "	3.5MM BTU Regen attached
<a href="#">T219P</a>	84" x 38'	1250		1983	100228-01-1		54152	0	Yes	No	" / "	
<a href="#">T150</a>	78" x 20'	1000		1962	62-3821-3			0	Yes	No	" / "	ABS tower w/ intgr. scrbr.
<a href="#">T294P</a>	78" x 31.5'	1300		1971	71-5984			0	Yes	No	" / "	
<a href="#">T348</a>	78" x 22.5'	1320		1965	CG-1378I-0-203				Yes		" / "	
<a href="#">T363P</a>	78" x 55'	1440		2001	01141101				Yes	No	" / "	
<a href="#">T95P</a>	72" x 31'	1200		1980	14792			0	Yes	No	" / "	glycol contactor
<a href="#">T266</a>	72" x 60'	500		2003	1627		1496	0	Yes	No	" / "	Amine Contact Tower
<a href="#">T315</a>	72" x 17'	1440		1970	70-626			0	Yes	No	" / "	
<a href="#">T311P</a>	72" x 32'	1440		1975	300825-01-01		17				" / "	Amine Gas Contactor Repaired by Rama /1994
<a href="#">T391P</a>	72" x 59.6'	1205		1967	7890		4593				" / "	
<a href="#">T285</a>	66" x 20'	1000		1993	83129		12165	0	Yes	No	" / "	
<a href="#">T292</a>	64" x 20'	1440		1972	A-47557			0	Yes	No	" / "	Tag only partially visible/very old
<a href="#">T360P</a>	62" x 54'	25		1981	2775-0		775				" / "	
<a href="#">T59</a>	60" x 24'	1000		1973	23576		62	0	Yes	No	" / "	
<a href="#">V372</a>	60" x 25'	1440		1995	PNPD360480		3112	0	Yes	No	" / "	Glycol Contactor

T202	60" x 13.5'	1440		1982	82-D-5702 CA			0	Yes	No	" / "	wt: 40k
T214	60" x 25'	1440		1966	CG-1460S-1728			0	Yes	No	" / "	Hemi Head
T268	60" x 66'	50		0000	0			0	Yes	No	" / "	Part of PL9; Amine Stripping STILL
T272	60" x 26'	1440		1982	82-D-5690-0A			0	Yes	No	" / "	
T273	60" x 20'	1440		1973	73-8271			0	No	No	" / "	
T274	60" x 27.5'	1440		1980	C08490A			0	No	No	" / "	
T350	60" x 24'	1200		1982	42816		7597		Yes	No	" / "	Repaired by: Atlas Products 2008 SN# 2530 Contact Tower ( Slurriss )
T379P	60" x 25'	1440		1979	1916						" / "	Glycol Contact Tower
T92	54" x 20'	1440		1980	T7347846-01			0	Yes	No	" / "	w/ exchanger / repaired by: Universal 1994
T114	54" x 24'	1440		1977	77-774		6372	0	Yes	No	" / "	7 tray tower; exchanger was cut off
T123	54" x 27.5'	1440		1988	HL-1V54701-01			0	Yes	No	" / "	
T125	54" x 25'	1440		1981	GPT-9750211-01			0	Yes	No	" / "	glycol contactor / repaired by: PESI 1991
T130	54" x 22'	1440		1973	73-48		3526	0	Yes	No	" / "	7 tray glycol absorber
T127	54" x 17.5'	1480		1987	TF-4026-A		606	0	Yes	No	" / "	
T126	54" x 19.5'	1480		1987	TF-4026-B		607	0	Yes	No	" / "	
T169	54" x 24'	1480		1990	90-14		19-998	0	Yes	No	" / "	wt: 53,500
T213	54" x 24'	1440		1991	N12B25001-01			0	Yes	No	" / "	
T226	54" x 25'	1440		1968	68-8711			0	Yes	Yes	" / "	60,000 + lb.
T229	54" x 24'	1440		1980	T-7223901-01			0	Yes	No	" / "	glycol absorber
T310P	54" x 20'	1440		1977	T-624900302			0	Yes	No	" / "	
T313	54" x 22.5'	1440		1982	GPT-9A82611-01			0	Yes	No	" / "	
T326P	54" x 25'	1440		1980	V-497			0	Yes	No	" / "	
T345	54" x 30'	748		1987	1T14702		1563		No	No	" / "	
T387P	54" x 25'	1440		2000	25196		383				" / "	Packed Glycol Cont.
T386P	49" x 12'	1100		1982	1496		507				" / "	Sulfa Treat Tower
T155P	48" x 27.5'	1480		1982	23817			0	No	No	" / "	ASME#10689-1; altered by: WPS 2000
T62	48" x 25'	1440		1982	A-71555			0	Yes	Yes	" / "	
T68	48" x 19.3333'	1440		1979	H-284			0	Yes	No	" / "	Glycol Gas Contactor
T69	48" x 22.5'	1440		1983	GP-835			0	Yes	No	" / "	8 tray
T77	48" x 27.5'	1440		1997	97-1412		2738590705	0	No	Yes	" / "	
T80	48" x 40.5'	0		1997	17496			0	No	No	" / "	Int. scrubber
T110	48" x 40'	0		2003	001203			0	No	No	" / "	
T129	48" x 22'	1440		1975	75A-1420			0	Yes	No	" / "	glycol gas contactor
T141	48" x 27.5'	1440		2002	A01-1213		143	0	No	No	" / "	8 tray tower
T142	48" x 22.5'	1480		1989	B-058-06-01		49	0	Yes	No	" / "	8 tray tower; wt=41klbs
T160	48" x 25'	1440		1988	88-1004			0	Yes	No	" / "	sulfa treat
T162	48" x 22'	1440		1968	CC-1448-2114			0	Yes	No	" / "	

<a href="#">T181</a>	48" x 14'	1440		1975	75-A1985			0	Yes	No	" / "	gas glycol contractor
<a href="#">T212</a>	48" x 25'	1440		1978	T6878005-01			0	Yes	No	" / "	Repaired by National Tank
<a href="#">T231P</a>	48" x 30'	1440		1989	2757		634	0	Yes	No	" / "	2 Manways & 2 Manway Covers
<a href="#">T258</a>	48" x 25'	1440		1973	0			0	Yes	No	" / "	
<a href="#">T259</a>	48" x 22.5'	1440		1983	GPT-7514302			0	Yes	No	" / "	
<a href="#">T260</a>	48" x 22.5'	1440		1981	T-7533905-01			0	Yes	No	" / "	
<a href="#">T327P</a>	48" x 24'	0		0	67848		451	0			" / "	
<a href="#">T354</a>	48" x 27.5'	1440		1987	87-1081				No	No	" / "	
<a href="#">T364</a>	48" x 27.5'	1440		2000	00-593		30181		No	Yes	" / "	
<a href="#">T367</a>	48" x 27.5'	1440		2002	A01-1298		150		No	No	" / "	
<a href="#">T61P</a>	42" x 25'	1440		0000	58771-05-01			2	Yes	Yes	" / "	Repair: Universal 2002 / 2 phase glycol absorber
<a href="#">T154</a>	42" x 25'	1440		1973	73-39		3517	0	No	No	" / "	
<a href="#">T218</a>	42" x 25'	1440		2004	04-309		33868	0	No	No	" / "	
<a href="#">T250</a>	42" x 25'	1440		1974	91374			0	No	No	" / "	Missing Exchanger; Repaired by Smith in 1990; Repaired by Tysco in 1990
<a href="#">T328</a>	42" x 25'	1440		2006	2427			0	No	No	" / "	
<a href="#">T377P</a>	42" x 48'	300		1985	0076						" / "	
<a href="#">T104P</a>	36" x 20'	800		1963	415927			2	No	No	" / "	
<a href="#">T145</a>	36" x 27.5'	1000		1989	1X546-01-01		7391	0	No	No	" / "	8 tray tower
<a href="#">T148</a>	36" x 27.5'	1000		1991	12B21401-01		8336	0	No	No	" / "	8 tray tower
<a href="#">T172</a>	36" x 20'	1440		1995	95-87		24591	0	No	No	" / "	repaired by: Hanover 1995
<a href="#">T248</a>	36" x 25'	1440		2008	CL08-260		37720	0	No	No	" / "	Ready to Go
<a href="#">T287</a>	36" x 15'	0		0000	0			0	Yes	Yes	" / "	No tag
<a href="#">T314</a>	36" x 25'	1420		1999	272A			0		No	" / "	
<a href="#">T309</a>	36" x 35'	1440		2008	113752						" / "	
<a href="#">T389</a>	36" x 20'	1480		2012	81386-1		244		Yes	No	" / "	Sulfa Treat Tower
<a href="#">T388</a>	36" x 20'	1480		2012	81386-2		245		Yes	No	" / "	Sulfa Treat Tower
<a href="#">T392P</a>	36" x 30'	1440		2006	06-409					No	" / "	
<a href="#">T45</a>	30" x 22.5'	1440		1997	EL9U20501-02		12916	0	Yes	No	" / "	sump
<a href="#">T90</a>	30" x 20'	1440		2007	1001-630			0	No	No	" / "	
<a href="#">T101P</a>	30" x 25'	1440		2005	05-302		34949	0	No	No	" / "	wt: 11800 lbs./ abs scrubber 8 tray tower
<a href="#">T102P</a>	30" x 20'	1440		1989	89-487			0	No	No	" / "	wt: 10700 lbs. / ABS Scrubber
<a href="#">T116</a>	30" x 22'	1000		1989	390			0	No	No	" / "	dehy tower / internal scrubber
<a href="#">T120</a>	30" x 31'	1440		1991	91-263		21254	0	No	No	" / "	10 tray
<a href="#">T201</a>	30" x 20'	1440		1993	93-132		23016	0	No	No	" / "	
<a href="#">T217</a>	30" x 24'	1440		1990	1951		620	0	No	No	" / "	Missing Exchanger
<a href="#">T230</a>	30" x 25'	1440		2007	06-540 EXT 0 PSI		35916	0	No	No	" / "	
<a href="#">T263</a>	30" x 20'	1440		1974	74-441		4160	0	No	No	" / "	Has 8 inspection ports; Repaired by Superior Fabrication in 2009
<a href="#">T280</a>	30" x 25'	1440		2004	EL9FS1201-01			0	No	No	" / "	

<a href="#">T297</a>	30" x 19.5'	1440		1968	55672-01-01		17538	0	No	No	" / "	Need to change 3 flanges; Repaired by National Tank in 1991
<a href="#">T306P</a>	30" x 50'	0		1984	2624			0	No	No	" / "	Amine Still Column
<a href="#">T317</a>	30" x 20'	1440		1981	81-1446		12053			No	" / "	
<a href="#">T318</a>	30" x 20'	1440		1980	T9715701-04				No	No	" / "	
<a href="#">T319</a>	30" x 20'	1440		1984	84-116		156				" / "	
<a href="#">T361P</a>	30" x 52'	1200		1981	2773-0		773		Yes	No	" / "	
<a href="#">T365P</a>	30" x 56'	337		1981	1152						" / "	Demethanizer
<a href="#">T366</a>	30" x 15.3'	1440		2004	60004071				No	No	" / "	
<a href="#">T369</a>	30" x 25'	1440		1976	76-87		04099		No	No	" / "	Repaired By Hanover 1996
<a href="#">T373</a>	30" x 25'	1440		2009	CL08-1041		38499				" / "	
<a href="#">T301</a>	28" x 22'	1440		1997	EL 9U18801-05		12571	0	No	No	" / "	
<a href="#">T31</a>	24" x 30'	1440		2006	06-512			0	Yes	Yes	" / "	no tag
<a href="#">T34</a>	24" x 20'	1440		1991	91-505			0	Yes	No	" / "	
<a href="#">T39</a>	24" x 22.3333'	1440		1978	T-9373101-04			0	Yes	Yes	" / "	glycol reboiler
<a href="#">T41</a>	24" x 25'	1440		1972	T-1895201-02			0	Yes	No	" / "	
<a href="#">T46</a>	24" x 20'	1440		1969	6929			0	Yes	No	" / "	Sump Tank
<a href="#">T98</a>	24" x 20'	1440		1990	90-1335		21079	0	No	No	" / "	6 tray tower
<a href="#">T103P</a>	24" x 20'	1440		1985	EL-1N52501-01			0	No	No	" / "	repaired by: NATCO 11/88
<a href="#">T108</a>	24" x 20'	1440		1995	95377		24613	0	No	No	" / "	int. scrubber
<a href="#">T140</a>	24" x 20'	1440		1989	89-394			0	No	No	" / "	6BCT ABS/SCR
<a href="#">T185</a>	24" x 20'	1440		1990	90-1333		21,077	0	No	No	" / "	
<a href="#">T191</a>	24" x 20'	1440		1997	97-257		26436	0	No	No	" / "	
<a href="#">T198</a>	24" x 19.8'	1217		1970	70-78		2553	0	No	No	" / "	repaired by: Facilities 1995
<a href="#">T211</a>	24" x 20'	1440		1998	98-52		27799	0	No	No	" / "	Repaired by Traco in 2005
<a href="#">T216</a>	24" x 20'	1440		1983	83-1438		15058	0	No	No	" / "	
<a href="#">T254</a>	24" x 16'	1440		2003	03-472		33068	0	No	No	" / "	Ready to Go
<a href="#">T279</a>	24" x 23'	1440		1973	23-038			0	No	No	" / "	Repaired by:AE Industries in 1995;Production Facilities Equipment in 2005
<a href="#">T284</a>	24" x 25'	1350		0000	2295-2101			0	Yes	No	" / "	
<a href="#">T288</a>	24" x 25'	2160		2004	60004135		347	0	No	No	" / "	
<a href="#">T303P</a>	24" x 20.5'	1440		1980	80-1121		10022	0	No	No	" / "	
<a href="#">T307P</a>	24" x 50'	1200		1984	1276			0	No	No	" / "	Amine Contactor
<a href="#">T343</a>	24" x 34.4'	375		0	T501-592						" / "	Repair stamp TH Russell CO 2000 Product Stabilizer
<a href="#">T346</a>	24" x 30'	1440		2010	CL09-913				No	Yes	" / "	Packed Tower
<a href="#">T351</a>	24" x 25'	1440		2006	2280						" / "	Repaired : by Natco 2010
<a href="#">T355</a>	24" x 24'	1440		2005	W1429		1405		No	No	" / "	
<a href="#">T359</a>	24" x 30'	1440		2009	CL09442824035		38881		No	No	" / "	V Packed ABS Scrubber
<a href="#">T358</a>	24" x 30'	1440		2009	CL09-397		38843		No	No	" / "	V Packed ABS Scrubber
<a href="#">T356</a>	24" x 30'	1440		2009	CL09-223		38666		No	No	" / "	V Packed scrubber

T357	24" x 30'	1440		2009	CL09-59		38639		No	No	" / "	V-packed ABS Scrubber
T368	24" x 25'	1440		1440	90.315C		20196		No	No	" / "	
T371	24" x 30'	1440		2009	CL09-299		38784				" / "	
T372	24" x 30'	1440		2009	CL09-395		38844				" / "	
T376P	24" x 52.6'	1440		1982	EL9003301-01			20 tray			" / "	20 Tray Amine Tower
T378P	24" x 52.6'	1200		1981	0						" / "	
T381P	24" x 23.5'	0		0	0						" / "	Glycol Tower
T56	20" x 25'	1200		1989	1884		527	0	No	No	" / "	
T75	20" x 23.5'	1422		2007	EL9666401-01		41348	0	No	No	" / "	no exchanger
T84P	20" x 42'	0		0000	0			0	No	No	" / "	Vapor Recover Tower
T85	20" x 19'	1440		1972	72-172			0	No	No	" / "	
T133	20" x 18'	1422		1982	GPT-9A62001-17			0	No	No	" / "	repaired by: Universal 2007
T147	20" x 22'	1000		1989	SA106B			0	No	No	" / "	
T152	20" x 21.5'	1422		1997	EL9E21401-02		13367	0	No	No	" / "	
T222	20" x 19'	1403		1975	75-172L		4533L	0	No	No	" / "	
T232	20" x 25.5'	1422		1991	EL9D71701-01		8295	0	No	No	" / "	Good Exchanger
T234P	20" x 35'	1440		1984	GPT-9C21801-01		4439	0	No	Yes	" / "	10 gpm Amine/Glymene plant with R120/Repaired by CE Natco in 1985 and National Tank in 2002
T240P	20" x 20'	1440		1984	939-A			0	No	No	" / "	
T241	20" x 18'	1403		1979	1979			0	No	No	" / "	
T243	20" x 20'	1440		2006	2574			0	No	No	" / "	Exchanger is Good
T246	20" x 21'	1422		1981	GPT-9746101-01			0	No	No	" / "	Exchanger is Good, but missing flange; Repaired by Facilities in 1994
T251	20" x 19.75'	0		0000	0			0	No	No	" / "	No tag
T256	20" x 21.75'	1422		1980	GPT-9704101-20			0	No	No	" / "	Repaired by L.C.F.I. in 1980
T261	20" x 20'	1440		2002	01-1276		32064	0	No	No	" / "	
T271	20" x 25'	1440		2006	0		36082	0	No	No	" / "	Internal Scrubber
T278	20" x 28'	1440		0000	83-154		13774	0	No	No	" / "	
T304	20" x 20.5'	0		1984	84-1505(1?)		16, 60	0	No	No	" / "	Gas Glycol Heat Exchanger
T341	20" x 19'	1408		1975	75-1771		45381	0	No	No	" / "	Repaired by Tysco 1993
T335	20" x 25'	1422		1988	EL9D40701-06		5951	0	No	No	" / "	
T347	20" x 24'	1440		1991	91097				No	No	" / "	
T353	20" x 56.1'	500		2000	T502-592						" / "	Condensate Stabilizer
T382P	20" x 35'	1440		2007	EL9008001-02		40171				" / "	
T281	18" x 18'	1200		1978	1882			0	No	No	" / "	
T55	16" x 25'	1440		2003	EL9F11101-01		24241	0	No	No	" / "	
T72	16" x 15'	1440		1990	90306			0	No	No	" / "	Dehydrator
T137	16" x 21.5'	1440		2003	001-99			0	No	No	" / "	repaired by: Production Facilities 2009
T151	16" x 19'	1200		1966	661-98		1108	0	No	No	" / "	

<a href="#">T159</a>	16" x 20'	1440		2006	K65801			0	No	No	" / "	
<a href="#">T168</a>	16" x 21.5'	1440		2001	7692-32D	207		0	No	No	" / "	
<a href="#">T197</a>	16" x 25.6'	1440		1985	GPT9C46601-02	5352		0	No	No	" / "	
<a href="#">T200</a>	16" x 19'	1435		1982	82-548	12861		0	No	No	" / "	
<a href="#">T204</a>	16" x 23'	1440		2004	1596			0	No	No	" / "	
<a href="#">T210</a>	16" x 21.5'	1440		1985	ELT90 46501-05	5523		0	No	No	" / "	Repaired by Traco in 2005
<a href="#">T242</a>	16" x 15'	1440		1982	23777			0	No	No	" / "	Repaired by Traco in 2003
<a href="#">T253</a>	16" x 23.5'	1440		2007	S07-130	325		0	No	No	" / "	
<a href="#">T257</a>	16" x 16'	1200		1978	CT 78-421			0	No	No	" / "	Packed Tower
<a href="#">T282</a>	16" x 20'	1440		1972	72-374			0	No	No	" / "	
<a href="#">T289</a>	16" x 23.5'	1440		1987	87447C			0	No	No	" / "	Repaired by Hanover Co. in 1996 - SN: 3709
<a href="#">T298</a>	16" x 23'	1440		2010	007467-5			0	No	Yes	" / "	Packed Tower
<a href="#">T299</a>	16" x 23'	1440		2009	007467-1			0	No	No	" / "	Packed Tower
<a href="#">T370</a>	16" x 19'	14		1981	01004-05						" / "	
<a href="#">T375P</a>	16" x 23'	1440		1980	GPT-9734001-16						" / "	
<a href="#">T374P</a>	16" x 25'	1440		2008	EL9G87001-01						" / "	
<a href="#">T383P</a>	16" x 25'	1032		1983	N/A						" / "	
<a href="#">T384P</a>	16" x 35'	1440		1982	GPT 97962101-09						" / "	
<a href="#">T190</a>	12.75" x 15'	1440		1977	22287			0	No	No	" / "	repaired by: Facilities 2012
<a href="#">T244</a>	12.75" x 19.5'	1440		1987	87-102			0	No	No	" / "	
<a href="#">T380P</a>	12.75" x 23.5'	1440		2008	EL9K05201-01						" / "	Glycol Tower
<a href="#">T385P</a>	12.75" x 23.5'	1440		2011	EL1037000807-49806	63686					" / "	
<a href="#">T118</a>	12" x 25.5'	1440		1987	EL9D17401-07	6269		0	No	No	" / "	internal scrubber
<a href="#">T189</a>	12" x 15'	125		1983	0			0	No	No	" / "	
<a href="#">T221</a>	12" x 17'	1200		1973	73-158	3583		0	No	No	" / "	
<a href="#">T300</a>	12" x 12'	1440		1984	1029			0	No	No	" / "	
<a href="#">T99</a>	10.75" x 15'	1440		1981	23484			0	No	No	" / "	dehydrator
<a href="#">T207</a>	10.7" x 10'	1440		1981	23328			0	No	No	" / "	w/exchanger; Repaired by P.E.S.I. 1994
<a href="#">T339</a>	10" x 13.5'	1200		1986	414			0	No	No	" / "	
<a href="#">T340</a>	10" x 15'	785		1984	170983			0	No	No	" / "	
<a href="#">T134</a>	9" x 17'	1440		1980	D-02-08-00813-01			0	No	No	" / "	vertical packed ABS scrubber / wt: 1720
<a href="#">T182</a>	8.625" x 9.5'	1597		1988	84116-01A			0	No	No	" / "	absorber
<a href="#">T187</a>	8.625" x 14'	1440		2009	0			0	No	No	" / "	
<a href="#">T227P</a>	8.5" x 15'	1440		2006	79-0924			0	No	No	" / "	4" Clean out packed tower
<a href="#">T290</a>	8" x 18'	1440		1985	51381			0	No	No	" / "	Int. Scrub: Packed
<a href="#">T54P</a>	6" x 18'	1200		1978	S143			0	No	No	" / "	Glycol Packed Tower
<a href="#">T352</a>	6" x 20'	1200		1988	1816	438			No	No	" / "	Packed Tower w/exchanger
<a href="#">T194</a>	4.625" x 12.5'	0		0000	0			0			" / "	no tag
<a href="#">T265P</a>	0	770		1986	0144			0	Yes	No	" / "	Repaired by Hi-Tech Production Systems in July 2009

T390P	0	0		0	H207358						" / "	Condensate Flash Tower
-------	---	---	--	---	---------	--	--	--	--	--	-------	------------------------

Coolers												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
C31	145" x 30'	0		2007	2006B-6551-A		10957	0	Yes	No	" / "	wt: 41,780/model:1F30-121-2/16.56MMBTU/hr/2,900 bare sqft/SA-249-T304L
C30	140" x 14'	0		2007	06-18540			0	Yes	No	" / "	wt:23,000/1.96MMBTU/hr-1521 bare sqft-SA214 CS Tubes
C46	119" x 31'	1440		1997	R-2285-1-A			0	No	No	" / "	190 - 1 3/8 SST Tubes
C6	114" x 15'	1500		1979	R9411C			0	No	No	" / "	
C44	102" x 10'	0		1975	744515.1B			0	Yes	No	" / "	Model 93 AH
C29	96" x 26.5'	1350		1993	93C477-AC1		493	0	No	Yes	" / "	Dual
C40	96" x 10.5'	0		1997	976504			0	No	Yes	" / "	Model 1F 11-80-1
C26	74.5" x 3.25'	150		2012	12763101-1		73688	0	No	No	" / "	Model No.: 3614
C66	60" x 35.5'	1440		2000	001719.1		37993		No	No	" / "	
C11	57" x 12'	100		2006	36506-2			0	No	No	" / "	
C39	53" x 13'	1440		1991	A019-1			0	No	No	" / "	Model HL48-2-14
C22	8" x 54'	1250		1974	0			0	No	No	" / "	54x96x108 cooler
C28	7" x 6'	0		0000	112876			0	No	No	" / "	Model No.: ESH-36 8983
C18	2" x 40'	5000		1999	0			0	No	Yes	" / "	ambient cooler
C15	0" x 165.5' x 84'	3000		1996	96C649AC		777	0	No	No	" / "	high pressure
C16	0" x 165.5' x 84'	3000		1996	96C680-AC-B		817	0	No	No	" / "	high pressure
C21	0" x 118' x 79'	1287		2007	0738401-1			0	No	No	" / "	
C23	0" x 17' x 8'	1292		2003	030315-1			0	No	Yes	" / "	1" tubes
C25	0	1480		2004	040222.1		45698	0	No	No	" / "	model: 93AEH
C27	0	1620		2004	D8161			0	No	No	" / "	20 million natural gas driven cooler
C34	0	50		0000	0			0	No	No	" / "	Amine Reflux Condenser/Part of PL9
C33	0	150		0000	0			0	Yes	No	" / "	Lean Amine Cooler/part of PL9
C42	0	1265		1984	16-6576-1-VC		192508	0	No	Yes	" / "	
C43	0	1480		2004	2003332S1A		9572	0	No	No	" / "	Gas Cooler
C47	0	1440		1978	7845331		1216	0	No	No	" / "	Model 96AH

<a href="#">C48</a>	0	0		0000	068555			0	No	No	" / "	Model F12-93-1
<a href="#">C51</a>	0" x 20' x 7'	1440		1997	97358-1		1783	0	No	Yes	" / "	7'W x 20'L Model H72
<a href="#">C53</a>	0	1292		1999	1999C3161A			0	No	No	" / "	
<a href="#">C54</a>	0	1440		0	97359-1		1784	0	No	Yes	" / "	
<a href="#">C55</a>	0	1440		2000	2000C2431A				No	No	" / "	
<a href="#">C56</a>	0	1440		2006	2005B3701-A			0	No	No	" / "	
<a href="#">C58</a>	0" x 20' x 8'	6800		2008	31030000-003						" / "	Ambient Cooler
<a href="#">C35</a>	0	275		1999	30114-77642		14025		No	No	" / "	Total sqft 4396.8 Model Type M30-FO
<a href="#">C36</a>	0	275		0	30104-77941		13113		No	Yes	" / "	4396.8 sqft Model Type M30-FO
<a href="#">C37</a>	0	150		1996	30104-77940		13112		No	Yes	" / "	2150.1 sqft Model # M20-MFG
<a href="#">C38</a>	0	150		1996	30104-77943		13114		No	Yes	" / "	1171.1 sqft Model type M20-MFO
<a href="#">C64</a>	0" x 24' x 8'	0		0	0				No	No	" / "	1932 MM BTU/hr 1.745 MM BTU/hr
<a href="#">C67P</a>	0	1440		2008	P544.1						" / "	Water Cooler
<a href="#">C68P</a>	0	1440		2008	P544.2						" / "	Water Cooler
<a href="#">C69P</a>	0	1275		1984	84-197-1A						" / "	
<a href="#">C70P</a>	0	75		1969	69-15-20						" / "	Cooler for PL41p
<a href="#">C71P</a>	0	500		0	0						" / "	

Deck / M.O.P.U.												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">DE1P</a>	0	0		0000	0			0			" / "	Shallow Water Jackup
<a href="#">DE2P</a>	0	0		0000	0			0	Yes	No	" / "	

Exchangers												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">E14</a>	45" x 14'	900		1976	S-18067			0	Yes	No	" / "	
<a href="#">E27</a>	42" x 20'	0		0	0						" / "	No tag
<a href="#">E16</a>	41" x 24'	0		1975	49074-1			0	No	No	" / "	Cold Gas Exchanger
<a href="#">E5</a>	30" x 16'	1440		2001	01-296		6077	0	No	Yes	" / "	L.P. Cooler (seawater cooler) / 1800 sq/ft tube surface area
<a href="#">E29</a>	28" x 30'	1100		1962	62-76						" / "	Feed Gas Exchanger
<a href="#">E15</a>	27" x 10'	403		1984	1760-01		1126	0	No	No	" / "	
<a href="#">E25</a>	27" x 12'	403		1984	1760-01		1126		No	No	" / "	Shell & Tube Exchanger
<a href="#">E32</a>	27" x 29.1'	0		0	3747A						" / "	Dry Gas Exchanger
<a href="#">E9</a>	24" x 16'	1480		2002	1560		387	0	No	No	" / "	Tube; Repaired by SMIC Companies in 2004



<a href="#">E8</a>	24" x 16'	1480		2002	1560.2		388	0	No	No	" / "	Tube; Repaired by SMI Companies in 2004
<a href="#">E10</a>	24" x 40'	1200		2001	5010		712	0	No	No	" / "	National Gas C
<a href="#">E12</a>	23" x 20'	100		1982	4191--1/RAMA 2606			0	No	No	" / "	Amine Exchanger/Part of PL9 Model AE7 Surface1010 SG FT Heavy Duty 10,200,000 BTU/HR - 261 SA-214 Tubes 3/4" Diam X.085 MW x 20' long
<a href="#">E13</a>	23" x 20'	100		1982	4191-2/RAMA 2606			0	No	No	" / "	Amine Exchanger/Part of PL9e Model AE7 Surface 1010 SG FT10,200,000 BTU/HR(261) SA-214 Tubes 3/4" Diam X.08/5 MW x 20' Long
<a href="#">E24P</a>	15" x 26.875'	175		2013	0						" / "	Regen Gas Heater 1044 square feet Tube side design test pressure 1135 Tube side inlet/outlet 4" 600 Shell side inlet/outlet 3" 600
<a href="#">E18</a>	10" x 40'	1440		2001	1202			0	No	No	" / "	
<a href="#">E4</a>	8" x 15'	4000		1964	4433			0	No	No	" / "	Pipe & Pipe
<a href="#">E30</a>	8" x 12'	375		2000	E206-592		643				" / "	Cond. Stabil. Reboiler Shell 375 Tube 250
<a href="#">E11</a>	0	1250		2004	231473		34639	0	No	Yes	" / "	11-A-240
<a href="#">E20P</a>	0	1000		1996	618.1			0	No	Yes	" / "	Liquid Gas Separator/Chiller Exchanger
<a href="#">E23</a>	0	1050		1974	74-148-A						" / "	
<a href="#">E28</a>	0	0		2000	E205-592						" / "	Condensate Stabilizer Exchanger
<a href="#">E31</a>	0	250		1962	62-77						" / "	Chiller TH Russel CO 2000 R2621
<a href="#">E33P</a>	0	13.403 MBTU/HR		1969	6632-1						" / "	
<a href="#">E34P</a>	0	75		1969	S-15899						" / "	
<a href="#">E36P</a>	0	0		1969	6632-2						" / "	

Filters												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">FS156</a>	66" x 10'	1300		1975	11422		7105		No	No	" / "	Contains 116 FG372 Elements Model 70H-116-FG372
<a href="#">FS15</a>	60" x 12.5'	860		1987	W-131		58	0	Yes	Yes	" / "	
<a href="#">FS16</a>	60" x 15.5'	812		1955	483		383	0	Yes	Yes	" / "	36,000 lbs
<a href="#">CF30P</a>	60" x 10'	0		0	0			0			" / "	
<a href="#">FS11</a>	48" x 10'	150		2000	133302		37676	0	Yes	No	" / "	
<a href="#">FS35</a>	48" x 10'	1440		0000	0			0	Yes	No	" / "	
<a href="#">CF31</a>	48" x 10'	125		1973	73-8284			0	Yes	No	" / "	Charcoal Filter
<a href="#">FS150</a>	42" x 9'	1420		1980	T-735		10038	0	Yes	No	" / "	
<a href="#">CF21</a>	42" x 4.5'	125		1977	24243		9672	0	No	Yes	" / "	
<a href="#">FS151</a>	42" x 12'	125		1986	86-063		7883		No	Yes	" / "	
<a href="#">CF5</a>	36" x 5'	220		1977	24346		9846	0	Yes	No	" / "	horizontal separator
<a href="#">FS60</a>	36" x 7.5'	1440		1975	T-4338408-01			0	Yes	No	" / "	

<a href="#">ES75</a>	36" x 10'	1440		1973	0	7025	0	Yes	No	" / "		
<a href="#">ES98</a>	36" x 8.5'	1218		1981	3601	296	0	No	No	" / "		
<a href="#">ES97</a>	36" x 8.5'	1218		1982	3715		0	No	No	" / "	Horizontal	
<a href="#">ES105</a>	36" x 15'	1440		1980	T-732 5517-01		0	Yes	Yes	" / "	Filter Separator - Horizontal	
<a href="#">ES133</a>	36" x 9'	1440		1976	1475		0	No	No	" / "	Repaired by RAMA in 1994	
<a href="#">ES136</a>	36" x 12'	1440		1970	422533			No	No	" / "		
<a href="#">ES153</a>	36" x 10'	1300		2006	06-531		35973	No	No	" / "		
<a href="#">ES161P</a>	36" x 5.17'	600		2004	8433-3		4806	No	No	" / "	Model# FF3624008 (7 identical pieces currently available.)	
<a href="#">ES30</a>	32" x 10'	1480		1991	6018		1246	0	No	No	" / "	gas filter separator
<a href="#">ES13</a>	30" x 7.5'	1000		2007	1063		1922	0	Yes	No	" / "	
<a href="#">ES21</a>	30" x 16'	403		1989	57234		10943	0	No	No	" / "	
<a href="#">ES45</a>	30" x 10'	1440		1995	5230		1143	0	No	No	" / "	
<a href="#">ES50</a>	30" x 11'	1440		1995	5231		0	No	No	" / "		
<a href="#">ES55</a>	30" x 10'	1100		1978	77-978		0	No	No	" / "		
<a href="#">CF20</a>	30" x 4'	150		2000	142943-1		38485	0	No	No	" / "	
<a href="#">ES80</a>	30" x 12.5'	720		2011	CL11-1620		42929	0	Yes	No	" / "	Ready to Go
<a href="#">ES93</a>	30" x 14'	720		1969	1049		0	No	No	" / "	Horizontal; Good Filter	
<a href="#">ES143</a>	30" x 12.5'	1440		2000	00-176		29773		No	Yes	" / "	
<a href="#">ES137P</a>	30" x 15'	1395		2008	03490-3		2635		No	No	" / "	
<a href="#">ES167P</a>	30" x 10'	1440		2000	25192		391	Filter		" / "	Vertical Filter Separator	
<a href="#">ES32</a>	29" x 5'	125		1978	25258		0	No	No	" / "	repaired by: Universal 1991	
<a href="#">ES29</a>	28" x 9'	1480		1987	87-1049-1		21791	0	No	No	" / "	gas filter separator / weight: 8900lbs
<a href="#">ES61</a>	28" x 9'	1200		1962	21725		0	No	No	" / "	repaired by: Atlas Products 1995	
<a href="#">CF29</a>	28" x 4'	150		1997	948802		34252	0	No	No	" / "	Model 10-3-44-28-150
<a href="#">ES154</a>	28" x 12.5'	1440		1979	79310		5571			" / "	Model # KTVSW 28-16	
<a href="#">ES160</a>	28" x 14'	1440		1979	79-310				No	No	" / "	
<a href="#">CF22</a>	25" x 5'	285		2001	200992		0	No	No	" / "	Fuel Gas Dryer	
<a href="#">ES10</a>	24" x 12.5'	960		1974	74-277		4044	0	Yes	No	" / "	
<a href="#">ES28</a>	24" x 7.5'	1480		1988	8-0074-1A		0	No	No	" / "	element filter	
<a href="#">ES27</a>	24" x 10'	1480		1988	8-0076-1A		0			" / "	element filter	
<a href="#">ES43</a>	24" x 12.5'	1440		1985	85-1146		18068	0	No	No	" / "	repaired by NATCO: 1996
<a href="#">ES54</a>	24" x 12.5'	1440		2005	D1266		266	0	No	No	" / "	
<a href="#">ES56P</a>	24" x 12.5'	1440		1984	84-871		15977	0	No	No	" / "	
<a href="#">CF17</a>	24" x 4'	0		0000	26191		0	No	No	" / "		
<a href="#">CF19</a>	24" x 4'	0		0000	23195		0	No	No	" / "	model: RFF-36-336; series: R	
<a href="#">ES71</a>	24" x 7'	1440		1997	EL9E19101-05		13018	0	No	No	" / "	
<a href="#">ES65</a>	24" x 12.5'	1440		1991	92-563		22.584	0	No	No	" / "	Repaired by Smith in 1993
<a href="#">ES88</a>	24" x 12.5'	1440		2001	D00.491		771	0	No	No	" / "	Horizontal
<a href="#">ES92</a>	24" x 9'	0		2007	AD-160		1198	0	No	No	" / "	Horizontal' Certified by BLM Equip. & Mfg.
<a href="#">ES100P</a>	24" x 10'	770		2009	HTP1314		0	Yes	No	" / "	Horizontal; with an 8" x 10' SS Tank	

<a href="#">FS102</a>	24" x 13.5'	1440		1999	12020/R2869			0	Yes	No	" / "	Horizontal; Part of PL9; Model 75H-1-F6372; Repaired by RAMA in 1999
<a href="#">FS109</a>	24" x 12.5'	1440		2000	00-506		30074	0	No	No	" / "	Filter Separator
<a href="#">FS135</a>	24" x 6'	1440		2008	NIP261						" / "	
<a href="#">FS134</a>	24" x 6'	1440		2008	NIP260						" / "	
<a href="#">FS162</a>	24" x 3.25'	150		2009	RD9981		2870		No	No	" / "	Model# 241404F1150C-C
<a href="#">FS163</a>	24" x 3.25'	150		2009	RD-9980		2869		No	No	" / "	Model# 241404F1150C-C
<a href="#">FS2</a>	20" x 10'	1440		2002	DN 99644		23671	0	Yes	No	" / "	
<a href="#">FS40</a>	20" x 9'	720		1998	98W0506		5629	0	No	No	" / "	
<a href="#">FS39</a>	20" x 9'	720		1998	98W0503		5626	0	No	No	" / "	
<a href="#">FS69</a>	20" x 12'	1440		2006	P1715		715	0	No	No	" / "	
<a href="#">FS70</a>	20" x 12'	1440		2005	P1418		418	0	No	No	" / "	
<a href="#">FS104</a>	20" x 4.5'	144		1979	T-7111608-01			0	No	No	" / "	Missing head; Repaired by Allen Tank in 1993; Horizontal
<a href="#">FS141</a>	20" x 14'	211		1975	12293		7407		No	No	" / "	Model 75H-8-FG372A
<a href="#">FS144</a>	20" x 12'	1440		2009	S9022		1105		No	No	" / "	
<a href="#">FS145</a>	20" x 12'	1440		2008	508-75		724		No	No	" / "	
<a href="#">FS146</a>	20" x 12'	1440		2009	08-7020		6048		No	No	" / "	
<a href="#">FS147</a>	20" x 12'	1440		2008	508-77		726		No	No	" / "	
<a href="#">FS148</a>	20" x 12'	1440		2007	V5838		1032		No	Yes	" / "	
<a href="#">FS164</a>	20" x 8.5'	1440		2000	99-927		29570		No	No	" / "	
<a href="#">FS165</a>	20" x 4.75'	1480		1995	95-590		24876				" / "	
<a href="#">FS116</a>	18" x 6.5'	125		0000	84-1014-1		18322	0	No	No	" / "	
<a href="#">FS130</a>	18" x 8.5'	1435		1980	80-354		9255	0	No	No	" / "	Horizontal
<a href="#">FS36</a>	16" x 11.2'	125		1975	GPT-433791701			0	No	No	" / "	single element vertical filter
<a href="#">FS58P</a>	16" x 5'	1440		2006	MM9T53701-01		34141	0	No	No	" / "	
<a href="#">FS83</a>	16" x 5'	1440		1985	85-1044		17,967	0	No	No	" / "	
<a href="#">CF24</a>	16" x 5'	1440		2005	EL9F83901-02		32308	0	No	No	" / "	EO5-1058
<a href="#">FS112</a>	16" x 6.5'	720		1984	8-1015-1		735	0	No	No	" / "	Horizontal; Repaired by PESI in 1996
<a href="#">FS117</a>	16" x 17.5'	1440		1980	16711		13281	0	No	No	" / "	
<a href="#">FS158</a>	16" x 7.5'	1000		2004	10979-05-01				No	No	" / "	
<a href="#">FS51</a>	14" x 6.5'	1440		2006	500806		3112	0	No	No	" / "	
<a href="#">CF16</a>	14" x 2'	150		2004	193493-3			0	No	No	" / "	
<a href="#">FS111</a>	14" x 6.5'	1440		0000	84-1016-1		1837	0	No	No	" / "	Horizontal; Model 75HGFG336
<a href="#">FS132</a>	14" x 7'	1440		0000	92-033		9386	0	No	No	" / "	Repaired by Hanover Co. in 2005
<a href="#">FS34</a>	12.75" x 8'	1440		2007	1001-763			0	No	Yes	" / "	horizontal gas coalescer
<a href="#">FS122</a>	12.75" x 8'	1440		1993	93465C		23235	0	No	No	" / "	
<a href="#">FS123</a>	12.75" x 4.25'	150		2008	E8697401-08		4G080	0	No	No	" / "	Vertical
<a href="#">FS131</a>	12.75"	1440		1992	92-031		9355	0	No	No	" / "	
<a href="#">FS85</a>	12" x 6'	3000		1983	84-632-1		17703	0	No	Yes	" / "	Horizontal
<a href="#">FS175</a>	10.75" x 8'	1440		2010	P2975		1975				" / "	
<a href="#">V911P</a>	10.75" x 5'	285		2006	60006033		739				" / "	
<a href="#">FS74</a>	10" x 9'	1000		1991	891-014			0	No	No	" / "	

<a href="#">FS78P</a>	10" x 6'	4700		1984	84-997-1		18202	0	Yes	No	" / "	Missing manway cap
<a href="#">CF27</a>	10" x 7.5'	1440		1996	2996			0	No	No	" / "	
<a href="#">FS81</a>	9" x 6.5'	500		2002	165152.1		41150	0	No	No	" / "	Good Condition; Vertical
<a href="#">FS174</a>	8.625" x 7.6'	1440		2005	V05-593		2248				" / "	
<a href="#">FS73</a>	8" x 6'	1440		2006	070406			0	No	No	" / "	
<a href="#">FS114</a>	8" x 7.5'	1440		2000	00W0473		6473	0	No	No	" / "	
<a href="#">FS140</a>	8" x 5.5'	1440		2007	MM918360102		38395	0	No	No	" / "	
<a href="#">FS159</a>	6.675" x 5.5'	250		2006	60006278				No	No	" / "	
<a href="#">FS139</a>	6.625" x 5.5'	1440		2011	CL11-715		41894	0	No	No	" / "	
<a href="#">FS138</a>	6.625" x 5.5'	1440		2011	C-11-713		41895	0	No	No	" / "	
<a href="#">FS166P</a>	6.625" x 6'	1440		1985	8518790						" / "	
<a href="#">FS168P</a>	0	0		0	1374						" / "	
<a href="#">FS169P</a>	0	0		0	0						" / "	
<a href="#">FS173P</a>	0	0		2005	05w0049						" / "	

Flare Stacks												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">FL11</a>	16" x 21'	0		0000	0			0	No	No	" / "	
<a href="#">FL12</a>	12" x 25.5'	0		0000	S 84029			0	No	No	" / "	
<a href="#">FL21</a>	10" x 25'	0		0	0				No	No	" / "	reduces from 10" to 4" Flare
<a href="#">FL22</a>	10" x 30'	0		0	641318						" / "	36" base OAL 65'
<a href="#">FL16</a>	4" x 10'	0		0	0			0			" / "	
<a href="#">FL18</a>	4" x 10'	0		0	0			0			" / "	4" 150 flange on end.
<a href="#">FL19</a>	4" x 10'	0		0	0			0			" / "	4" 150 flange on end
<a href="#">FL20</a>	4" x 10'	0		0	0			0			" / "	
<a href="#">FL15</a>	2" x 10'	0		0	0			0			" / "	12 volt
<a href="#">FL17</a>	2" x 10'	0		0	0			0			" / "	

Water Treatment Equipment												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">V831P</a>	120" x 33'	150		1993	2188			463			" / "	Oxygen Stripper Tower
<a href="#">FC111</a>	96" x 4'	175		1992	6682A		95	3	Yes	Yes	" / "	3 phase skimmer
<a href="#">EC113</a>	60" x 20'	7		1988	SM137A						" / "	Model AFS.10.3 Air Floatation System
<a href="#">EC112</a>	54" x 11.5'	0		1994	DL-50-3-010394-V1			0	Yes	No	" / "	

Fuel Gas Packages													
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info	
<a href="#">EGP9</a>	16" x 7'								275				
				1998	980368-3				0	No	Yes	" / "	Cold Separator

<a href="#">EGP10</a>	16" x 5'	1440		2006	1181		19	2	No	Yes	" / "	Filter is Good
<a href="#">EGP11</a>	16" x 7'	275		1998	980368-2						" / "	
<a href="#">EGP7</a>	6" x 4.5'	275		2006	0			0	No	Yes	" / "	Model: 85-1-FG12
<a href="#">EGP5</a>	0" x 10.75' x 5'	285		2004	03-851		3347710006	0	No	Yes	" / "	fuel gas package

Gas Units												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">GU2</a>	36" x 9'	6500		2001	LL8E24301-04			0	No	No	" / "	Vertical Scrubber
<a href="#">GU3</a>	30" x 6'	0		0000	0			0	No	Yes	" / "	no tag
<a href="#">GU4</a>	24" x 10'	1403		1984	47784		159	0	No	Yes	" / "	
<a href="#">GU7P</a>	2	0		2010	4150			0			" / "	2XXH-EXP.6.2XXH-7340 750K-GPU Coil PH.4
<a href="#">GU5</a>	0	0		1981	T-7671601-01			0	No	Yes	" / "	5'W x 5'6"H x 12'L
<a href="#">GU6</a>	0	0		1976	T-6166401-01			0	No	No	" / "	53"W x 63"H x 12'L
<a href="#">GU8P</a>	0	0		2008	4036-2			0			" / "	7340/EXP.6.2XXH.7740
<a href="#">GU9P</a>	0	0		2009	4036-1			0			" / "	7340/EXP.6.2XXH.7340
<a href="#">GU10P</a>	0	0		2009	A023-2			0			" / "	7340EXP.6.2XXH.73/0
<a href="#">GU11P</a>	0	0		2007	3782-2			0			" / "	EXP.4.2XXH-6500

Heater Treaters												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">HT48</a>	132" x 20'	50		1981	T-1A54401-02			0	Yes	No	" / "	
<a href="#">HT53</a>	120" x 25'	50		1977	646661-01						" / "	Acadiana Contractors 2006
<a href="#">HT5</a>	96" x 15'	50		1973	T-3219901-01			0	Yes	No	" / "	
<a href="#">HT20</a>	96" x 27'	50		0000	ELTIA52201-01			0	Yes	No	" / "	
<a href="#">HT34</a>	96" x 20'	75		1993	93-422			0	Yes	No	" / "	Horizontal
<a href="#">HT42</a>	96" x 20'	50		1982	GPT-1000110-01			0	Yes	Yes	" / "	
<a href="#">HT50</a>	96" x 25'	75		2002	01-1338		98971601	0	Yes	Yes	" / "	
<a href="#">HT10</a>	72" x 20'	50		2005	23368			0	Yes	No	" / "	
<a href="#">HT11</a>	72" x 20'	50		1993	093014			0	Yes	No	" / "	
<a href="#">HT29</a>	72" x 20'	50		1983	23867			0	Yes	Yes	" / "	Repaired by P.E.S.I. in 1997
<a href="#">HT31</a>	72" x 15'	125		1991	N-12B25501-01			0	Yes	Yes	" / "	
<a href="#">HT51</a>	72" x 15'	30		1989	HL-1X49601-01			0	Yes	Yes	" / "	
<a href="#">HT47</a>	72" x 20'	0		0000	0			0	Yes	No	" / "	
<a href="#">HT52</a>	72" x 20'	75		2008	1001-836				Yes	No	" / "	
<a href="#">HT49</a>	60" x 27'	50		2009	29026			0	Yes	No	" / "	Vertical
<a href="#">HT22</a>	48" x 27'	125		1989	89-263C			0	Yes	No	" / "	
<a href="#">HT21</a>	48" x 27'	125		1989	89-264C			0	Yes	No	" / "	wt: 8400lbs
<a href="#">HT23</a>	48" x 27'	125		1989	89-265C			0	Yes	No	" / "	
<a href="#">HT27</a>	48" x 27'	50		1985	85-4748		17397	0	No	No	" / "	no ladder

<a href="#">HT39</a>	48" x 10'	75		1984	84-D-6335-0A			0	Yes	No	" / "	
<a href="#">HT40</a>	0	0		2007	1375-2044		227	0	Yes	No	" / "	wt: 130K/ 16.1MMBTU/hr
<a href="#">HT41</a>	0	0		2007	1375-2045		228	0	Yes	No	" / "	wt: 94K / 4.92MMBTU/hr
<a href="#">HT54P</a>	0	0		0	0						" / "	part of PL41P
<a href="#">HT56P</a>	0	0		0	0						" / "	
<a href="#">HT55P</a>	0	0		0	0						" / "	

Horizontal Vessels												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">H563</a>	120" x 35'	40		1978	H253			0	Yes	No	" / "	Oil Surge Tank
<a href="#">H682</a>	120" x 25'	50		1971	D-1967001-02		7755	0	Yes	Yes	" / "	Repaired by Acadian Contractors in 2010
<a href="#">H748</a>	120" x 17'	252		1969	161842				Yes	No	" / "	
<a href="#">H749</a>	120" x 17'	252		1969	161841				Yes	No	" / "	
<a href="#">H396</a>	108" x 25'	1035		1969	422039			0	Yes	No	" / "	gas scrubber / wt: 180klbs
<a href="#">H395</a>	108" x 25'	1035		1969	422044			0	Yes		" / "	
<a href="#">H783</a>	108" x 27'	275		2001	1112.00		449		Yes	No	" / "	
<a href="#">H804P</a>	96.75" x 20'	108		1958	H-1954-58						" / "	
<a href="#">H740</a>	96" x 10'	125		1996	J-07_-01		487				" / "	
<a href="#">H751</a>	90" x 16'	645		1962	40747-62				Yes	No	" / "	
<a href="#">H769</a>	84" x 10'	75		1982	7282				Yes	Yes	" / "	
<a href="#">H311</a>	78" x 20'	125		1995	K95-125		3096	0	Yes	No	" / "	hot oil expansion drum
<a href="#">H552</a>	78" x 10'	1440		1978	78-A-4610			3	Yes	No	" / "	
<a href="#">H719</a>	78" x 15'	125		1989	B-17707-01			0	Yes	No	" / "	Horizontal Water Skimmer
<a href="#">H715</a>	78" x 10'	1440		1994	3027960802		136		Yes	No	" / "	Repaired by RAMA 1994 SN# 3027071002
<a href="#">H797</a>	78" x 19.2'	750		1982	F81-096		3150		Yes	No	" / "	OHSD Reactor Separator w/ 2' Boot
<a href="#">H185</a>	72" x 15'	151		1976	76-122B			0	Yes	No	" / "	Skimmer / repaired by General Fab 1999
<a href="#">H418</a>	72" x 13'	285		1981	1049			0	Yes	No	" / "	6' Air Eliminator
<a href="#">H466</a>	72" x 20'	230		0000	1558		252	0	Yes	No	" / "	repaired by: EPF 2007
<a href="#">H472</a>	72" x 14'	1108		1954	1550			0	Yes	Yes	" / "	Gas Dehydrator; Repaired by National Tank Co. 1997
<a href="#">H506</a>	72" x 15'	125		2000	3488C		266	0	Yes	No	" / "	Water Skimmer
<a href="#">H605</a>	72" x 15'	125		1979	679.2.929		8049	3	Yes	No	" / "	Repaired by Omega
<a href="#">H631</a>	72" x 15'	125		1985	85-D-6738-00			3	Yes	No	" / "	Skimmer
<a href="#">H673</a>	72" x 15'	125		1999	98-427		28928	0	Yes	No	" / "	
<a href="#">H678</a>	72" x 20'	275		1987	K-87-526		2001	0	Yes	No	" / "	Repaired by Shell Offshore in 1994
<a href="#">H679</a>	72" x 15'	125		1972	22.052			0	Yes	Yes	" / "	Repaired by National Tank Co. in 1996; Universal Equipment Inc. in 2000
<a href="#">H697</a>	72" x 20'	275		1986	1090		91	3	Yes	No	" / "	Water Skimmer
<a href="#">H786</a>	72" x 15'	125		2006	06-562		36047		Yes	Yes	" / "	
<a href="#">H803P</a>	72" x 14.6'	1205		1967	7888		4591				" / "	PL41

<a href="#">H262</a>	70" x 12.5'	125		1991	050191			0	Yes	No	" / "	2",4",6" in/outs
<a href="#">H519</a>	66" x 10'	125		1988	5288			0	Yes	No	" / "	Skimmer
<a href="#">H716</a>	66" x 20'	1600		1976	7984B-9129ECC	29			Yes	No	" / "	Service Glycol Contactor
<a href="#">H750</a>	66" x 16'	585		1962	40748-62				Yes	No	" / "	Oil Flash Tank
<a href="#">H802P</a>	66" x 12'	97		1967	0						" / "	Flare KO Drum
<a href="#">H805P</a>	66" x 20'	200		1980	9187		1635				" / "	part of PL41P amine flash tank
<a href="#">H527</a>	60.75" x 15'	125		1967	1108-67			3	Yes	No	" / "	Repaired by Streamline in 2010
<a href="#">H274</a>	60" x 15'	1250		1974	1009		368	0	No	No	" / "	coalescer
<a href="#">H275</a>	60" x 15'	1230		1974	T-3308904-01			3	Yes	No	" / "	repaired by: NATCO 1995
<a href="#">H287</a>	60" x 15'	150		1987	87-1620		19365	0	Yes	No	" / "	vent scrubber / weight: 8600lbs
<a href="#">H304</a>	60" x 20'	2025		1995	2455		627	0	Yes	No	" / "	wt: 60klbs
<a href="#">H309</a>	60" x 15'	150		1974	T-3308			0	Yes	No	" / "	water skimmer
<a href="#">H429</a>	60" x 20'	495		1957	49851			0	No	No	" / "	
<a href="#">H471</a>	60" x 15'	125		1969	69-143			0	Yes	Yes	" / "	Water Skimmer
<a href="#">H462</a>	60" x 20'	1440		1976	T-6718402-02			0	Yes	No	" / "	Repaired by EPF 2007
<a href="#">H559</a>	60" x 20'	125		1982	C527			3	Yes	Yes	" / "	Vessel as one patch; Repaired by Tysco in 1987
<a href="#">H606</a>	60" x 15'	1440		1970	CV1621			3	Yes	No	" / "	Repaired by Rheem Superior in 1996
<a href="#">H612</a>	60" x 20'	1440		1975	75-A1590			3	Yes	Yes	" / "	
<a href="#">H659</a>	60" x 15'	275		1986	NIT 1R29405.01			0	Yes	No	" / "	
<a href="#">H676</a>	60" x 15'	125		1968	68-527-1			0	Yes	No	" / "	Gas Scrubber; Repaired by Cembell Industries in 1994
<a href="#">H693</a>	60" x 20'	1440		1983	GPT-1G53002-01			0	Yes	No	" / "	
<a href="#">H694</a>	60" x 20'	1800		1963	63 4549-1			3	No	No	" / "	
<a href="#">H713</a>	60" x 15'	1480		1989	0	29	0	0	Yes	No	" / "	Weight 49,500
<a href="#">H717</a>	60" x 10'	1350		2001	AC-087		3610		Yes	No	" / "	
<a href="#">H742</a>	60" x 20'	712		1964	80910				Yes	No	" / "	
<a href="#">H777</a>	60" x 20'	300		1979	79-126-1				No	Yes	" / "	Repaired by Natco 1999
<a href="#">H239</a>	54" x 10'	1480		1984	16292		10147	3	Yes	No	" / "	
<a href="#">H250</a>	54" x 10'	2000		1960	4633		1917	0	No	No	" / "	repaired by: Spitzer Industries 2000
<a href="#">H306</a>	54" x 20'	1440		0000	0			0	Yes	No	" / "	no tag info
<a href="#">H461</a>	54" x 15'	1440		1971	CV-1864			3	Yes	Yes	" / "	
<a href="#">H554</a>	54" x 15'	0		0000	0			0	No	No	" / "	No tag
<a href="#">H621</a>	54" x 15'	125		2001	60001057	44	3	3	Yes	No	" / "	
<a href="#">H647</a>	54" x 15'	125		1994	G06104-01			3	Yes	No	" / "	
<a href="#">H658</a>	54" x 15'	1440		1994	793-A	155	0	0	Yes	No	" / "	
<a href="#">H710</a>	54" x 10'	740		1999	99-036		11442	0	No	No	" / "	Knockout Sump on bottom; Good MistPad
<a href="#">H720</a>	54" x 10'	1440		1981	GPT-1A74913-01			0	Yes	No	" / "	23000lbs
<a href="#">H792</a>	54" x 10'	1440		1990	020002-01				Yes	Yes	" / "	
<a href="#">H115</a>	48" x 15'	720		1998	EL2D98803-06	14391	0	0	Yes	No	" / "	B-tex Buster 150
<a href="#">MH67-216</a>	48" x 8'	1440		1978	9933 ECC		code	3	No	No	" / "	4" Flanges & WP of 3200 / 7800

<a href="#">H168</a>	48" x 12.5'	1200		1964	2764		762	0	Yes	No	" / "	HD2 Unidryer / Repair: Bagwell Brothers 1997
<a href="#">H208</a>	48" x 10'	1440		1975	55075			3	Yes	No	" / "	repaired by: Omega 1997
<a href="#">H233</a>	48" x 10'	125		2001	9873A		318	0	No	No	" / "	wt: 3620lbs
<a href="#">H281</a>	48" x 7.5'	125		1990	F652174			0	Yes	No	" / "	
<a href="#">H292</a>	48" x 12.5'	1440		1982	82-D-5877-0A			3	No	No	" / "	water skimmer
<a href="#">H315</a>	48" x 15'	25		1988	88-133-1A			0	Yes	No	" / "	water skimmer
<a href="#">H350</a>	48" x 10'	125		2003	60003058		238	0	Yes	Yes	" / "	skimmer
<a href="#">H360</a>	48" x 8'	125		1981	0042-3-16-14			0	Yes	No	" / "	volume tank (closed system cooling storage tank)
<a href="#">H389</a>	48" x 10'	125		2001	01-437		31673	3	Yes	Yes	" / "	skimmer
<a href="#">H402</a>	48" x 15'	275		1978	78-88		1089	0	Yes	No	" / "	
<a href="#">H404</a>	48" x 15'	275		1990	C26508-01			0	Yes	No	" / "	L.P. surge separator
<a href="#">H407</a>	48" x 12.5'	1440		1985	85-2152		19075	3	Yes	No	" / "	
<a href="#">H409</a>	48" x 12.5'	1440		1985	85-2151		19074	3	Yes	No	" / "	
<a href="#">H403</a>	48" x 15.5'	1440			0000	0		0	No	No	" / "	tag not readable
<a href="#">H410</a>	48" x 23'	1261		1981	62170-73			0	Yes	No	" / "	power gas bottle
<a href="#">H419</a>	48" x 15'	1440		1972	CV-2305			0	Yes	Yes	" / "	repaired by: Rama 1990
<a href="#">H422</a>	48" x 10'	720		1995	0			0	Yes	Yes	" / "	no MFR
<a href="#">H453</a>	48" x 15'	150		1995	2140		298	3	Yes	No	" / "	repaired by: Coastline Process 1993
<a href="#">H459</a>	48" x 20'	150		1981	T-7652509-01			0	Yes	Yes	" / "	repaired by: A.F. Industries 1994
<a href="#">H485</a>	48" x 15'	150		1985	85-21-85 C		19108	2	No	No	" / "	water skimmer
<a href="#">H479</a>	48" x 10'	1440		1990	HL 2A672-01			0	No	Yes	" / "	
<a href="#">H507</a>	48" x 10'	125		2002	60002018		143	0	Yes	No	" / "	Skimmer
<a href="#">H548</a>	48" x 15'	125		1995	95-452		24738	3	Yes	Yes	" / "	Water Skimmer; Ready to Go
<a href="#">H575</a>	48" x 20'	1200		1965	69264-B		566	2	No	No	" / "	
<a href="#">H576</a>	48" x 20'	600		1988	1215		182	0	Yes	No	" / "	Amine Flash Separator; Part of PL9; Repaired by Alter Rama in 1999; New Serial #98-005
<a href="#">H609</a>	48" x 20'	350		1969	69-156		2277	3	No	No	" / "	Repaired by Tysco in 1990
<a href="#">H608</a>	48" x 15'	1440		1965	NB738			3	Yes	No	" / "	
<a href="#">H618</a>	48" x 12.5'	1480		2001	201198			0	Yes	Yes	" / "	
<a href="#">H630</a>	48" x 15'	125		2005	05-141		35059	0	Yes	Yes	" / "	Water Skimmer
<a href="#">H633</a>	48" x 10'	125		2004	1001-218			3	No	Yes	" / "	
<a href="#">H648</a>	48" x 15'	1440		1983	83-1506 1A			0	No	No	" / "	
<a href="#">H646</a>	48" x 15'	1440		1998	668-A		64	0	No	No	" / "	
<a href="#">H650</a>	48" x 15'	0		1993	1765			0	Yes	No	" / "	
<a href="#">H657</a>	48" x 20'	1300		1975	P-113			0	Yes	No	" / "	
<a href="#">H664</a>	48" x 10'	125		2001	01-438		31729	0	Yes	Yes	" / "	Repaired by Offshore Specialty Fab in 2008
<a href="#">H677</a>	48" x 15'	1440		1994	501-89-172			0	Yes	No	" / "	Repaired by Campbell Industries Inc. in 1994
<a href="#">H681</a>	48" x 15'	125		2002	02-262		32442	0	Yes	Yes	" / "	



<a href="#">H683</a>	48" x 15'	125	1998	9107A	254	0	Yes	No	" / "	Water Skimmer
<a href="#">H686P</a>	48" x 15'	1440	0000	0		0	Yes	Yes	" / "	
<a href="#">H700</a>	48" x 10'	125	2006	25543	662	0	Yes	Yes	" / "	Water Skimmer
<a href="#">H703</a>	48" x 15'	1440	1983	23911		3	Yes	No	" / "	Repaired by The Shaw Group Inc. in 2001
<a href="#">H718</a>	48" x 20'	1440	1988	A062-03-01			Yes	No	" / "	
<a href="#">H721</a>	48" x 20'	1440	1988	A06202-01		0	Yes	No	" / "	38,000lbs dry weight
<a href="#">H753</a>	48" x 15.5'	1300	1950	14-148			Yes	No	" / "	
<a href="#">H754</a>	48" x 15'	1440	1968	421378			Yes	No	" / "	Repaired by Natco 1979 Repaired by RAMA 1993
<a href="#">H767</a>	48" x 15'	100	1999	3213/A			Yes	No	" / "	
<a href="#">V826P</a>	48" x 8'	150	1981	2776-C	776		Yes	Yes	" / "	
<a href="#">H776</a>	48" x 15'	125	1998	97-1575	27540		Yes	Yes	" / "	
<a href="#">H778</a>	48" x 10'	142	1984	2846011			Yes	No	" / "	
<a href="#">H781</a>	48" x 20'	250	2000	V406-592		3	No	No	" / "	
<a href="#">H782</a>	48" x 14.7'	250	1959	3339			Yes	No	" / "	Rino Equipment inc. 1990
<a href="#">H785</a>	48" x 10'	125	1998	98-122			Yes	Yes	" / "	Horizontal Skimmer
<a href="#">H787</a>	48" x 10'	1440	2007	BR67-289	1160	3	Yes	No	" / "	Offshore separator
<a href="#">H788</a>	48" x 10'	1440	2007	60006234	943	3	Yes	Yes	" / "	
<a href="#">H794</a>	48" x 15'	1400	2013	CLB13-47	46626		No	Yes	" / "	
<a href="#">H796</a>	48" x 12'	350	1990	58800	11287	3	Yes	Yes	" / "	3-Phase Test Separator
<a href="#">H161</a>	42" x 15'	125	1977	9014-1	774	3	Yes	No	" / "	
<a href="#">H180</a>	42" x 24'	165	1979	91-186-01-01	50	0	Yes	No	" / "	
<a href="#">H243</a>	42" x 10'	1440	1990	F652-170		0	Yes	No	" / "	repaired by: OMEGA 2001
<a href="#">H252</a>	42" x 10'	1440	1972	72-7215-1		3	No	No	" / "	repaired by: A.F. Industries
<a href="#">H286</a>	42" x 10'	1440	1968	421408		3	No	No	" / "	
<a href="#">H363</a>	42" x 10'	125	1998	97-1580	27545	3	No	No	" / "	
<a href="#">H385</a>	42" x 15'	1440	1973	CV2560		0			" / "	
<a href="#">H384</a>	42" x 15'	1440	1975	T-5223501-01		3	No	No	" / "	repaired by: Tysco 1993
<a href="#">H430</a>	42" x 20'	500	1957	49843		0	No	No	" / "	
<a href="#">H436</a>	42" x 10'	100	1971	71-66		0	Yes	No	" / "	
<a href="#">H439</a>	42" x 10'	125	1977	77-152-L		0	Yes	No	" / "	
<a href="#">H537</a>	42" x 15'	1440	2007	CL07-836	37276	2	No	No	" / "	Repaired by KW International in 2009
<a href="#">H545</a>	42" x 15'	1200	1959	411913		2	No	No	" / "	Repaired by Lafitte Welding in 1987
<a href="#">H603</a>	42" x 12'	1440	1979	79-106	7863	3	Yes	No	" / "	
<a href="#">H635</a>	42" x 10'	1440	1991	24543	4845	3	Yes	No	" / "	3 Phase
<a href="#">H639</a>	42" x 12.6'	1480	1991	0	11	0	Yes	Yes	" / "	Repaired by Offshore Specialty Fabricators
<a href="#">H652</a>	42" x 10'	1440	1968	421405	1298	0	No	No	" / "	Repaired by Bagwell Brothers in 1998
<a href="#">H685</a>	42" x 10'	1440	1991	24541		0	Yes	No	" / "	Repaired by Offshore Specialty in 2000
<a href="#">H722</a>	42" x 10'	1440	1982	GPT-9A82604-01		3	No	No	" / "	3 Phase
<a href="#">H726</a>	42" x 15'	1440	1983	GPT-1G59001-01		0	Yes	No	" / "	
<a href="#">H745</a>	42" x 10'	1440	1981	GPT-9750104-01		3	No	No	" / "	3 Phase

H752	42" x 15'	770		1991	V412-592				Yes	No	" / "	Surge Tank Repaired by TH Russel 2000 stamp R2621
H766	42" x 8'	1440		1979	8179				Yes	Yes	" / "	Repaired by Universal Equipment 2001
H770	42" x 15'	50		2001	3343						" / "	
H775	42" x 15'	1440		1979	79-A-5195				Yes	Yes	" / "	
H779	42" x 16'	770		1963	79994				Yes	No	" / "	TH Russell Co. 2000 R2621
H784	42" x 11.75'	1440		1972	T-1579604-01		2		Yes	Yes	" / "	Repaired by Coastline Equip. Inc. 1988
H789	42" x 10'	125		1995	1907A		3		Yes	No	" / "	
H790	42" x 10'	1480		2001	2115-V				Yes	No	" / "	
WTP001-14	42" x 10'	1440		2014	GPT-1M21502-01	5315					" / "	
WTP002-14	42" x 10'	1440		2014	GPT-1G03502-01						" / "	
WTP003-14	42" x 10'	1440		2014	GPT-1J42502-01						" / "	
WTP004-14	42" x 10'	1440		2014	0						" / "	
WTP005-14	42" x 10'	1440		2014	0						" / "	
H793P	42" x 12.6'	740		1993	120593						" / "	Pressure Vessel
H798P	42" x 10.2'	1440		1997	95521-1	34130					" / "	Horizontal inlet filter sep
H118	36" x 8'	125		1972	T1452914-01		3		No	No	" / "	repaired by: CF&S Tank Co 1994
H32	36" x 10'	125		0000	67970	code	3		No	Yes	" / "	2-phase Decassing Sep.
H257	36" x 15'	1440		2001	01-623	31417	0			No	" / "	
H272	36" x 10'	1440		0000	0		3		No	No	" / "	Repair: Universal 1994
H279	36" x 15'	1440		2002	02-20	32198	3		No	Yes	" / "	
H283	36" x 10'	1440		1971	423511		2		No	No	" / "	repaired by: General Fab 1996
H294	36" x 10'	1440		1974	T-3308901-01		3		No	No	" / "	
H301	36" x 10'	1440		1999	F99409		3		No	Yes	" / "	
H310	36" x 7.5'	1440		1975	T-5128904-01		2		No	Yes	" / "	
H405	36" x 10'	1440		1990	C26505-0		3		No	No	" / "	
H406	36" x 10'	1440		1990	C26504-01		3		No	No	" / "	
H420	36" x 10'	2160		0000	60005036	726	0		Yes	Yes	" / "	
H454	36" x 10'	1440		1979	23239		3		Yes	No	" / "	repaired by: Coastline Process 1993
H452	36" x 10'	1440		1982	40490	1176	0		Yes	No	" / "	
H464	36" x 10'	500		1983	GPT-1G85006-01		0		No	No	" / "	
H474	36" x 6'	175		2008	533407	3902	0		No	No	" / "	Instrument Air Receiver
H494	36" x 10'	250		1997	EL 9U21201-03		0		No	No	" / "	Repaired by National Tank Co. in 1997
H493	36" x 10'	250		1997	EL9U21201-02		3		No	Yes	" / "	
H502	36" x 10'	1800		1997	97-10	125	3		No	No	" / "	Repaired by PESI in 2004
H513	36" x 10'	1440		2005	60004245	584	3		No	Yes	" / "	
H526	36" x 10'	1440		1981	81-1198-A		0		Yes	No	" / "	
H523	36" x 10'	1440		1968	68-198		3		Yes	No	" / "	Repaired by Dolphin Services Inc. in 2001
H553	36" x 10'	1440		1980	23280		3		Yes	Yes	" / "	
H567	36" x 10'	1440		1995	3134C	142	3		No	Yes	" / "	Looks Good
H614	36" x 10'	1440		2007	BRO 7-181	1209	3		Yes	Yes	" / "	Skid is Good
H624	36" x 15'	1440		0000	99678	29807	3		No	No	" / "	

<a href="#">H644</a>	36" x 10'	1440		1977	GPT 6473514-01			0	No	No	" / "	
<a href="#">H655</a>	36" x 15'	1440		1997	97-1002		27041	0	Yes	No	" / "	
<a href="#">H667</a>	36" x 10'	1440		1977	77A-3494			0	No	Yes	" / "	Repaired by Coastline Process Equip Inc. in 1988 - SN: 1354-ALT.
<a href="#">H671</a>	36" x 10'	1440		1976	6044301-01			0	Yes	Yes	" / "	Repaired by Universal Equipment in 2006; Coastline Process in 1989 and National Tank in 1976
<a href="#">H674</a>	36" x 10'	1480		1987	87137-A			0	No	Yes	" / "	Repaired by Pesi in 1990; Allen Process Systems in 2004
<a href="#">H684</a>	36" x 10'	1480		1998	33680		225	3	Yes	No	" / "	
<a href="#">H695</a>	36" x 15'	1440		1983	23 909			0	Yes	No	" / "	
<a href="#">H701</a>	36" x 10'	1440		2007	2876			2	Yes	No	" / "	Repaired by DBI Welding on 9/5/13
<a href="#">H707</a>	36" x 10'	1440		2005	05-3-386		114	0	Yes	No	" / "	
<a href="#">H709</a>	36" x 10'	2160		2005	60005017		443	3	No	No	" / "	
<a href="#">H711</a>	36" x 9.75'	125		1983	4482		1098	2	No	Yes	" / "	Repaired by RAMA in 1994
<a href="#">H723</a>	36" x 10'	1480		2000	200372			3	Yes	No	" / "	Repaired by Magnolia Ind. Fab in 2002
<a href="#">H724</a>	36" x 17'	525		1984	2220-G			0	Yes	No	" / "	
<a href="#">H738</a>	36" x 15'	1440		2001	01-146		31344	3	Yes	Yes	" / "	
<a href="#">H757P</a>	36" x 10'	125		2015	15295-103						" / "	
<a href="#">H758P</a>	36" x 10'	125		2014	15006-106						" / "	
<a href="#">H759P</a>	36" x 10'	125		2015	15236-101						" / "	
<a href="#">H760P</a>	36" x 10'	125		2015	15250-102						" / "	
<a href="#">H761P</a>	36" x 10'	125		2015	15236-102						" / "	
<a href="#">H762P</a>	36" x 10'	125		2014	15006-108						" / "	
<a href="#">H763P</a>	36" x 10'	1440		2012	1206-01		35	3			" / "	
<a href="#">H764P</a>	36" x 10'	1440		2012	1108-02		26	3			" / "	Trailer Mounted
<a href="#">H774</a>	36" x 10'	1440		1972	T-1540805-01				No	No	" / "	Repaired by Coastline Process 1987
<a href="#">H780</a>	36" x 20'	315		1964	V408-592				No	No	" / "	Originally built by Stearns Roger Corp. in 1964 no SN# available repaired by TH Russell in 2000 Refrigerant Accumulator
<a href="#">H795</a>	36" x 10'	1440		2000	25193		392	Filter			" / "	Horizontal 3-Phase Separator
<a href="#">h807p</a>	36" x 10'	1440		2006	v06-369		2826			Yes	" / "	on skid with H806P
<a href="#">H53</a>	30" x 6'	240		1984	3773			3	Yes	No	" / "	Repaired by Pesi 1984 Repaired by Universal 2002
<a href="#">H173</a>	30" x 12'	125		1994	LW-582		133	2	No	No	" / "	Glycol condensation separator
<a href="#">H229</a>	30" x 15'	1440		1969	CV1160			3	No	Yes	" / "	repaired by: Atlas Products 2002
<a href="#">H298</a>	30" x 15'	1440		1968	421471			2	No	No	" / "	
<a href="#">H354P</a>	30" x 12'	5500		1969	69-9428			2	No	No	" / "	repaired by: Universal 1991
<a href="#">H390</a>	30" x 10'	1440		1965	C-613			3	No	No	" / "	bucket and weir / Repaired by: Coastline Process Equipment 1990
<a href="#">H414</a>	30" x 10'	125		1967	29790			2	No	Yes	" / "	repaired by: Coastline Process 1989
<a href="#">H413</a>	30" x 10'	1440		1967	420356			2	No	Yes	" / "	repaired by: Universal 1990
<a href="#">H432</a>	30" x 10'	2000		1968	68-212		2043	2	No	No	" / "	repaired by: Tysco 1986
<a href="#">H433</a>	30" x 10'	2000		1970	70-227		2690	2	No	No	" / "	

<a href="#">H465</a>	30" x 7.5'	1440		1983	GPT-1G85007-01			2	No	No	" / "	
<a href="#">H511</a>	30" x 10'	1440		1977	T-6534503-01			3	No	No	" / "	Repaired by General Fabricators, Inc. in 2004
<a href="#">H522</a>	30" x 10'	1440		1968	68-8599-1			3	No	No	" / "	Repaired by Dolphin Services Inc. in 2001
<a href="#">H530</a>	30" x 10'	1200		1964	417287			2	No	Yes	" / "	
<a href="#">H531</a>	30" x 7.5'	1440		1982	82-1370-1A		0019	3	Yes	No	" / "	
<a href="#">H541</a>	30" x 10'	1440		2002	EL9E99301-01		22089	3	No	No	" / "	clean
<a href="#">H480</a>	30" x 10'	1440		0000	1176-2-1994			3	No	Yes	" / "	
<a href="#">H578</a>	30" x 10'	500		2011	21109-190			2	No	Yes	" / "	
<a href="#">H581</a>	30" x 10'	500		2011	21110-063			2	No	Yes	" / "	
<a href="#">H582</a>	30" x 10'	500		2008	2803-27			2	No	Yes	" / "	
<a href="#">H583</a>	30" x 10'	500		2007	1007-404			2	No	Yes	" / "	
<a href="#">H584</a>	30" x 10'	500		2011	21101-008			2	No	Yes	" / "	
<a href="#">H585</a>	30" x 10'	500		2011	21107-271			2	No	Yes	" / "	
<a href="#">H586</a>	30" x 10'	500		2011	21106-078			2	No	Yes	" / "	
<a href="#">H587</a>	30" x 10'	500		2012	12-1146			2	No	Yes	" / "	
<a href="#">H588</a>	30" x 10'	500		2010	21005-098			2	No	Yes	" / "	
<a href="#">H590</a>	30" x 10'	0		0000	0			2	No	Yes	" / "	
<a href="#">H591</a>	30" x 10'	500		2007	0707-257			2	No	Yes	" / "	
<a href="#">H592</a>	30" x 10'	500		2007	0			2	No	Yes	" / "	
<a href="#">H593</a>	30" x 10'	500		2012	21111-307			2	No	Yes	" / "	
<a href="#">H594</a>	30" x 10'	500		2007	0407-063			2	No	Yes	" / "	
<a href="#">H596</a>	30" x 10'	500		2007	0707-215			2	No	Yes	" / "	
<a href="#">H599</a>	30" x 10'	1440		2008	1H630 0101			2	No	No	" / "	
<a href="#">H600</a>	30" x 10'	500		2007	2333			2	No	Yes	" / "	
<a href="#">H604</a>	30" x 10'	1440		1981	81-1149-6A			3	No	No	" / "	Head Cut Off
<a href="#">H645</a>	30" x 10'	1440		1978	6761901-01			3	Yes	No	" / "	
<a href="#">H643</a>	30" x 10'	1440		1990	20220		50	3	No	No	" / "	
<a href="#">H642</a>	30" x 15'	1440		1980	79 846		8601	3	No	No	" / "	
<a href="#">H665</a>	30" x 10'	1480		1994	G06102-01			3	Yes	No	" / "	
<a href="#">H663</a>	30" x 10'	1440		2002	01-322		32358	3	Yes	No	" / "	
<a href="#">H680</a>	30" x 10' x 1440'	0		2002	01-318		32335	3	Yes	Yes	" / "	
<a href="#">H702</a>	30" x 10'	1200		1960	412487			2	No	Yes	" / "	
<a href="#">H704</a>	30" x 15'	2025		1984	84-1168		16274	3	No	No	" / "	
<a href="#">H746</a>	30" x 7.5'	1000		1982	GPT-1F03401-01			2	No	No	" / "	
<a href="#">H768</a>	30" x 8'	1440		1982	1482						" / "	Repaired by Universal 1984 Integricert 2013 Tare Weight 23,000
<a href="#">H771</a>	30" x 8'	1440		1982	1382				No	Yes	" / "	
<a href="#">H791</a>	30" x 10'	1440		1966	C952				No	No	" / "	
<a href="#">FS170P</a>	30" x 10.75'	1185		1969	1106		1038				" / "	Inlet Filter Sep
<a href="#">H806P</a>	30" x 10'	125		2006	06-146		35519			Yes	" / "	on skid with H807P
<a href="#">CB1</a>	26" x 15'	1930		2003	02466-3A		19027	0	No	No	" / "	wt: 9439lbs

<a href="#">CB2</a>	26" x 15'	1930	2003	02466-3B	19028	0	No	No	" / "	wt: 9439lbs
<a href="#">CB3</a>	26" x 15'	1930	2003	02467-3A	19034	0	No	No	" / "	wt: 9439lbs
<a href="#">CB4</a>	26" x 15'	1930	2003	02467-3B	19035	0	No	No	" / "	wt: 9439lbs
<a href="#">CB6</a>	26" x 13.2'	1045	2003	02466-2A	19025	0	No	No	" / "	wt: 5114lbs.
<a href="#">CB7</a>	26" x 13.2'	1045	2003	02467-2B	19033	0	No	No	" / "	wt: 5114lbs.
<a href="#">H154</a>	24" x 7.5'	1440	1966	419304		2	No	Yes	" / "	
<a href="#">H82</a>	24" x 7.5'	125	1984	50-84-1672-1A	code	3	No	No	" / "	Repair: Process Equip. Services Co.
<a href="#">H200</a>	24" x 7.5'	125	1991	91-440C	21431	3	No	Yes	" / "	
<a href="#">H282</a>	24" x 7.5'	150	1988	8-0079		3	No	No	" / "	
<a href="#">H289</a>	24" x 10'	2000	1977	66321-1-01		3	No	No	" / "	repaired by: Burner Fire Control 2007
<a href="#">H305</a>	24" x 10'	1440	1967	67277	1558	3	No	No	" / "	repaired by: Allen Tank 1989
<a href="#">CB5</a>	24" x 13.2'	1045	2003	02466-2B	19026	0	No	No	" / "	wt: 5114lbs.
<a href="#">H364</a>	24" x 7'	225	1982	1034		3	Yes	No	" / "	
<a href="#">H435</a>	24" x 10'	1440	1976	2422	838	2	No	No	" / "	
<a href="#">H437</a>	24" x 10'	1440	1977	T-6515601-13		2	No	No	" / "	
<a href="#">H438</a>	24" x 10'	1440	1977	T-6515601-17		2	No	No	" / "	
<a href="#">H444</a>	24" x 10'	1380	1987	457		2	No	No	" / "	
<a href="#">H445</a>	24" x 10'	1440	2000	00-316	30019	2	No	No	" / "	
<a href="#">H469</a>	24" x 7.5'	1440	1979	T-9436001-01		3	No	No	" / "	
<a href="#">H478</a>	24" x 10'	1440	2006	40928-64		2	No	Yes	" / "	
<a href="#">H484</a>	24" x 10'	125	1985	2172A		3	No	No	" / "	
<a href="#">H496</a>	24" x 10'	1440	1977	22807		3	No	Yes	" / "	
<a href="#">H492</a>	24" x 8'	1440	1993	81-188		3	No	No	" / "	Repaired by Lafitte Welding Works in 1993
<a href="#">H486</a>	24" x 10'	1440	1969	422321		2	No	No	" / "	Repaired by National Tank Co. in 1978
<a href="#">H504</a>	24" x 10'	1440	1982	T-ID39919-01		3	No	No	" / "	Repaired by Universal Equipment in 1984
<a href="#">H521</a>	24" x 10'	1440	1983	83-253	13873	2	No	No	" / "	
<a href="#">H538</a>	24" x 10'	1440	2001	EL9U45201-01	20009	3	No	No	" / "	
<a href="#">H539</a>	24" x 10'	125	1961	61-3463-1		2	No	No	" / "	
<a href="#">H572</a>	24" x 10.5'	1440	1980	80-8574.C		3	No	Yes	" / "	
<a href="#">H579</a>	24" x 10'	1440	2006	40928-55		2	No	Yes	" / "	
<a href="#">H580</a>	24" x 10'	1440	2005	40928-7		2	No	Yes	" / "	
<a href="#">H597</a>	24" x 7.5'	125	2008	EL9F89001-01	34093	3	No	No	" / "	
<a href="#">H598</a>	24" x 8'	1000	2006	1006-013-A	804	2	No	No	" / "	
<a href="#">H622</a>	24" x 10'	1440	1974	21547	437	2	No	No	" / "	
<a href="#">H632</a>	24" x 10'	1440	1978	6708601-01		3	No	No	" / "	
<a href="#">H634</a>	24" x 10'	1440	0000	0		3	No	Yes	" / "	Repaired by Universal Equipment in 2003
<a href="#">H638</a>	24" x 10'	1440	1978	708 602		3	No	No	" / "	
<a href="#">H651</a>	24" x 10'	1440	1988	L-1V56609		3	No	No	" / "	
<a href="#">H668</a>	24" x 10'	125	1990	90-0343		3	No	Yes	" / "	
<a href="#">H689</a>	24" x 10'	1440	1985	ELT IL 55901-01	4584	3	No	Yes	" / "	

<a href="#">H688</a>	24" x 7'	1440	1981	94 09001-04		3	No	Yes	"/ "	
<a href="#">H691</a>	24" x 7.5'	125	1981	23653		3	No	No	"/ "	
<a href="#">H698</a>	24" x 10'	1200	1962	415070		2	No	Yes	"/ "	Repaired by National Tank Co. in 1998
<a href="#">H735</a>	24" x 10'	1440	2007	MM9M02901-01	40447	2	No	No	"/ "	
<a href="#">H756</a>	24" x 7.5'	1440	1979	7181501-C1			No	No	"/ "	
<a href="#">H765</a>	24" x 10'	1440	1968	421457			No	No	"/ "	Repaired by Universal Inc 1996
<a href="#">H106</a>	20" x 7.5'	1422	1981	9A32101-05	2440	3	No	No	"/ "	vent scrubber
<a href="#">H190</a>	20" x 7.5'	1422	1978	0		3	No	No	"/ "	
<a href="#">H201</a>	20" x 7.5'	1440	1991	91-3950	21386	2	No	Yes	"/ "	
<a href="#">H335</a>	20" x 6'	4500	1965	NB718		0	No	No	"/ "	sand trap
<a href="#">H443</a>	20" x 7.5'	1440	2000	00-736	30276	2	No	No	"/ "	
<a href="#">H455</a>	20" x 7.5'	1422	1979	T-9421501-01		3	No	No	"/ "	repaired by: Facilities 2000
<a href="#">H456</a>	20" x 7.5'	1440	1989	0		3	No	No	"/ "	repaired by: Facilities 1999
<a href="#">H457</a>	20" x 10'	1440	1976	20468		3	No	No	"/ "	
<a href="#">H470</a>	20" x 7.5'	1422	1978	0		3	No	No	"/ "	
<a href="#">H500</a>	20" x 10'	1403	1988	45872	252	2	No	No	"/ "	
<a href="#">H514</a>	20" x 7.5'	1400	1986	59180101		3	No	Yes	"/ "	
<a href="#">H528P</a>	20" x 7.5'	1440	1986	86-364		2	No	No	"/ "	
<a href="#">H529P</a>	20" x 7.5'	1440	1986	86-360		2	No	No	"/ "	
<a href="#">H568</a>	20" x 7.5'	1403	1979	79505		2	No	No	"/ "	
<a href="#">H623</a>	20" x 7.5'	1440	2004	2056		2	No	No	"/ "	
<a href="#">H692</a>	20" x 7.5'	1422	1968	421508		2	No	Yes	"/ "	Repaired by National Tank Co. in 1996
<a href="#">H733</a>	20" x 10'	1440	1971	CV2110		2	No	No	"/ "	
<a href="#">H736</a>	20" x 7.5'	1440	2000	00737	30304	2	No	Yes	"/ "	
<a href="#">H122P</a>	16" x 5'	1100	1995	ELT9079601-06	5554	0	No	No	"/ "	
<a href="#">H44</a>	16" x 10'	1440	0000	T-5000404-01	code	2	Yes	No	"/ "	
<a href="#">H318</a>	16" x 7.5'	1440	2004	1004048		0	No	No	"/ "	
<a href="#">H334</a>	16" x 7.5'	1000	1976	689		0	No	Yes	"/ "	
<a href="#">H536</a>	16" x 10'	1435	1977	77.279	5877	2	No	No	"/ "	
<a href="#">H544</a>	16" x 10'	1440	1993	998	646	2	No	Yes	"/ "	
<a href="#">H542</a>	16" x 5'	0	0000	0		2	No	Yes	"/ "	
<a href="#">H558</a>	16" x 7.5'	1440	1983	616C		2	No	No	"/ "	
<a href="#">H566</a>	16" x 7.5'	1440	2001	01-1211	31883	2	No	No	"/ "	
<a href="#">H628</a>	16" x 7.5'	1200	1987	60817		2	No	Yes	"/ "	
<a href="#">H669</a>	16" x 8'	1440	1984	40774		2	No	Yes	"/ "	
<a href="#">H727</a>	8.625" x 12'	1000	2013	1001-2321		0	No	No	"/ "	Horizontal Volume Bottle
<a href="#">H801P</a>	6.6" x 24'	50	1970	9374					"/ "	Flare Gas/Liquid Sep
<a href="#">ES171P</a>	0	0	0	0					"/ "	inlet filter
<a href="#">H808P</a>	0	1440	2006	06-15				Yes	"/ "	on skid with H809P
<a href="#">H809P</a>	0	0	2006	06-25				Yes	"/ "	on skid with H809P

Lact Units												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
Lact4	16" x 4'	275		1997	316 V97-01		395	2	No	Yes	" / "	Singer Meter AL-800
Lact2	0	150		0000	0			0	No	Yes	" / "	Has pump/charcoal filter/3" 150 E-body w/box
Lact3	0	0		0000	9752232			0	No	Yes	" / "	Meter as 4"/4" in/out

Line Heaters												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
LH189	108" x 25'	6mmBTU		2009	0						" / "	
LH163	102" x 18'	0		1991	8492			0	No	Yes	" / "	Weight: 9200 lbs.
LH133	96" x 32.5'	3		2011	606211			0	No	Yes	" / "	60,000 lbs./No stacks/Oil Heater
LH76	72" x 24'	25		1980	34289			0	No	Yes	" / "	4MM BTU w/ stack Direct Fired
LH162	72" x 18'	0		0000	0			0	No	Yes	" / "	No tag
LH187	72" x 26'	0		1971	P-2084201-01						" / "	
MLH2-36	66" x 20'	10000		0000	2348985			0	Yes	Yes	" / "	829lb empty
LH82	66" x 12'	0		0000	0			0			" / "	no tag
LH122	60" x 20'	0		2005	14-1001			0	No	No	" / "	No stack
LH150	60" x 17.5'	0		1981	T-1A55116-01			0	Yes	Yes	" / "	
LH157	60" x 12'	0		1969	19.909			0	No	No	" / "	Model# 1H-6012-160
LH158	60" x 12'	0		1995	91868			0	No	Yes	" / "	
LH177	60" x 20'	0		2007	489120001				No	Yes	" / "	
LH188	60" x 18'	0		1981	T-1A55118-01				No	Yes	" / "	Well 1 Upstream Coil 10,000 PSI Size 3.5" OD downstream 1440 size 4.5" OD Well 2 Upstream Coil 10,000 PSI Size 3.5" OD downstream 1440 size 3.5" OD
LH191P	60" x 12'	1.5mm		1982	7059						" / "	
LH27	48" x 17.5'	7800		2004	5954			0	No	No	" / "	No firetube
LH44	48" x 12'	10000		1965	207			0	No	Yes	" / "	
LH65	48" x 7.5'	3705		2000	3023			0	No	Yes	" / "	broken choke
LH69	48" x 10'	6500		1996	0			0	No	No	" / "	no stack; 750M BTU
LH73	48" x 10'	12		1984	48758			0	No	Yes	" / "	1MM BTU w/ skid and stack
LH80	48" x 10'	0		0000	0			0	No	Yes	" / "	no tag
LH83	48" x 10'	3		1981	4055			0	No	Yes	" / "	no stack
LH85	48" x 10'	5000		2007	F-27100			0	No	No	" / "	
LH103	48" x 17.5'	10000		0000	0			0	Yes	No	" / "	no process coil
LH119	48" x 17.5'	0		2003	4645			0	No	Yes	" / "	
LH117	48" x 15.5'	0		0000	T-1099103-01			0	No	No	" / "	No tag; No stack
LH127	48" x 10'	0		1998	LH 4164.11.98			0	No	No	" / "	
LH128	48" x 10'	0		1991	C-5097			0	No	Yes	" / "	
LH149	48" x 17.5'	0		1997	1021			0	Yes	Yes	" / "	
LH161	48" x 15'	0		1970	0			0	No	No	" / "	No shell tag
LH174	48" x 17.5'	0		1999	2239			0	No	Yes	" / "	

<a href="#">LH002-14</a>	48" x 17.5'	0		1987	298573			0		Yes	"/ "	Trailer mounted rental unit Trailer Vin # 624277
<a href="#">LH178</a>	48" x 17.5'	0		2001	3276				No	Yes	"/ "	
<a href="#">LH183</a>	48" x 10'	0		2008	CEB-159-2008				No	No	"/ "	12 Pass 3"XXH 5000lb coil 2009 has Choke
<a href="#">LH184</a>	48" x 17.5'	0		2004	5115				No	Yes	"/ "	
<a href="#">LH186</a>	48" x 10'	0		2008	2806-248						"/ "	Coils 4 Pass Pre 10,000 PSI 6 Pass Expansion 1480PSI
<a href="#">LH62</a>	42" x 12'	15000		2008	8252			0	No	No	"/ "	
<a href="#">LH74</a>	42" x 14'	6170		2004	D-488530015			0	No	Yes	"/ "	
<a href="#">LH89</a>	42" x 14.5'	0		2003	4501			0	No	Yes	"/ "	
<a href="#">LH90</a>	42" x 14.3'	0		2004	6039			0	No	Yes	"/ "	
<a href="#">LH116</a>	42" x 14.5'	0		2001	4025			0	No	Yes	"/ "	No Stack
<a href="#">LH153</a>	42" x 14.25'	0		1978	13613			0	No	Yes	"/ "	
<a href="#">LH173</a>	42" x 14.3'	0		1998	1593			0	No	Yes	"/ "	
<a href="#">LH182</a>	42" x 10'	0		1959	59-1190						"/ "	has choke 6000 PSI coils
<a href="#">LH185</a>	42" x 15'	0		2007	31030005						"/ "	
<a href="#">LH34</a>	36" x 10'	3000		1993	2886001-04			0	No	Yes	"/ "	
<a href="#">LH37</a>	36" x 10'	6000		1982	IH4409			0	No	No	"/ "	
<a href="#">LH39</a>	36" x 10'	5000		2005	2230			0	No	Yes	"/ "	
<a href="#">LH49</a>	36" x 10'	6500		1990	EL9D64301-01			0		Yes	"/ "	no stack
<a href="#">LH53</a>	36" x 10'	6500		1990	9D61701-06			0		Yes	"/ "	no stack
<a href="#">LH61</a>	36" x 10'	6000		1981	C12825			0	No	Yes	"/ "	repaired by: Production Facilities 2009
<a href="#">LH63</a>	36" x 10'	0		1999	9710901-05			0	No	No	"/ "	750k BTU
<a href="#">LH64</a>	36" x 12'	10000		2005	7130			0	No	Yes	"/ "	
<a href="#">LH72</a>	36" x 10'	6170		1983	46398			0	No	No	"/ "	
<a href="#">LH75</a>	36" x 12'	7800		2005	4235			0	No	Yes	"/ "	750MBTU
<a href="#">LH88</a>	36" x 10'	0		1999	31007882			0	No	No	"/ "	
<a href="#">LH94</a>	36" x 10'	0		1987	687-002			0	No	Yes	"/ "	
<a href="#">LH101</a>	36" x 10'	0		2006	406-182			0	No	Yes	"/ "	
<a href="#">LH107</a>	36" x 12'	0		1985	27005			0	No	No	"/ "	Hole on side where fire tube is
<a href="#">LH118</a>	36" x 12'	0		2001	4036			0	No	No	"/ "	
<a href="#">LH124</a>	36" x 10'	0		1998	EL9U27601-01			0	No	No	"/ "	Has clean coils
<a href="#">LH136</a>	36" x 10'	6400		1984	2650			0	No	No	"/ "	
<a href="#">LH137</a>	36" x 10'	6400		1986	2890			0	No	No	"/ "	
<a href="#">LH138</a>	36" x 10'	0		1989	9D56602-03			0	No	No	"/ "	
<a href="#">LH139</a>	36" x 10'	0		0000	LH213-604			0	No	No	"/ "	
<a href="#">LH141</a>	36" x 10'	0		1987	1R 94801-05			0	No	No	"/ "	
<a href="#">LH165</a>	36" x 10'	0		1986	60572			0	No	Yes	"/ "	
<a href="#">LH154</a>	36" x 12'	0		2003	5012			0	No	Yes	"/ "	
<a href="#">LH156</a>	36" x 12'	0		2009	006830-5			0	No	No	"/ "	
<a href="#">LH166</a>	36" x 10'	0		1978	30 201			0	No	Yes	"/ "	Repaired by Production Facilities Equip in 2004
<a href="#">LH175</a>	36" x 10'	0		1984	48621			0	No	Yes	"/ "	Model TH-3610-12
<a href="#">LH181</a>	36" x 10'	0		1999	9Z11301-01					No	"/ "	
<a href="#">LH56</a>	30" x 10'	6500		1988	EL9D39101-01			0		Yes	"/ "	no stack



<a href="#">LH148</a>	30" x 10'	0		1985	27101			0	No	Yes	" / "	
<a href="#">LH146</a>	30" x 10'	0		2003	7005			0	Yes	No	" / "	
<a href="#">LH167</a>	30" x 10'	0		1993	40138			0	No	Yes	" / "	
<a href="#">LH179</a>	28" x 10'	250M		1999	2612			0	No	Yes	" / "	shop # 8606901
<a href="#">LH152</a>	26" x 10'	0		0000	0			0	No	Yes	" / "	No Tag
<a href="#">LH142</a>	24" x 10'	6000		1987	70102			0	No	Yes	" / "	
<a href="#">LH144</a>	24" x 7'	0		1974	9556			0	No	Yes	" / "	
<a href="#">LH190P</a>	0	2.0mm		0	0					Yes	" / "	

Miscellaneous												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">SVS1</a>	156" x 48.6'	0		2006	0			0	No	Yes	" / "	wt: 98,100/with 3 Removal Beds, Dry Gas Cooler, Gas Cooler Compressor, Regen Heater and Gas Cooler
<a href="#">SS1</a>	144" x 40'	0		2006	0			0	Yes	No	" / "	wt: 56,000/with 2 Gas Cooler Scrubbers, Gas Cooler and Gas Cooler Compressor
<a href="#">NDUS1</a>	120" x 30.5'	0		0000	0			0	Yes	No	" / "	wt: 58,000/ with:2 Nitrogen Dryer Beds and Nitrogen Heater
<a href="#">HM1P</a>	96" x 19'	150		1979	0				No	No	" / "	Steam Boiler Model 5-5-2506-5150GP
<a href="#">PIG7</a>	48" x 12'	0		0	0						" / "	8" x 6"
<a href="#">WTP001-14</a>	42" x 10'	1440		2014	GPT-1M21502-01		5315				" / "	
<a href="#">WTP002-14</a>	42" x 10'	1440		2014	GPT-1G03502-01						" / "	
<a href="#">WTP003-14</a>	42" x 10'	1440		2014	GPT-1J42502-01						" / "	
<a href="#">WTP004-14</a>	42" x 10'	1440		2014	0						" / "	
<a href="#">WTP005-14</a>	42" x 10'	1440		2014	0						" / "	
<a href="#">CB1</a>	26" x 15'	1930		2003	02466-3A		19027	0	No	No	" / "	wt: 9439lbs
<a href="#">CB2</a>	26" x 15'	1930		2003	02466-3B		19028	0	No	No	" / "	wt: 9439lbs
<a href="#">CB3</a>	26" x 15'	1930		2003	02467-3A		19034	0	No	No	" / "	wt: 9439lbs
<a href="#">CB4</a>	26" x 15'	1930		2003	02467-3B		19035	0	No	No	" / "	wt: 9439lbs
<a href="#">CB6</a>	26" x 13.2'	1045		2003	02466-2A		19025	0	No	No	" / "	wt: 5114lbs.
<a href="#">CB7</a>	26" x 13.2'	1045		2003	02467-2B		19033	0	No	No	" / "	wt: 5114lbs.
<a href="#">CB5</a>	24" x 13.2'	1045		2003	02466-2B		19026	0	No	No	" / "	wt: 5114lbs.
<a href="#">VRU4</a>	14" x 4'	150		2010	72			2	No	No	" / "	
<a href="#">VRU3</a>	12" x 4'	150		2009	42010			2	No	Yes	" / "	
<a href="#">TMGCU1P</a>	0	0		2009	0			0	Yes	No	" / "	2009 Foam Unit with Superior Booster; 314 hours since new
<a href="#">TMGCU2P</a>	0	0		2010	0			0	Yes	No	" / "	2010 Foam unit with superior booster; 17 since new
<a href="#">TMGCU3P</a>	0	0		2007	0			0	Yes	No	" / "	2007 Foam Unit w/CIP booster. 1242 Hours since new
<a href="#">VSP1</a>	0	1700		0000	C-121086			0	No	No	" / "	8.75 Bore; 5.5 Stroke
<a href="#">VSP2</a>	0	1700		0000	0			0	No	No	" / "	Bore 11.375; Stroke 6.5
<a href="#">VSP3</a>	0	1700		0000	C-120995			0	No	No	" / "	8.75 Bore; 6.5 Stroke

VSP4	0	1700		0000	C-121085			0	No	No	" / "	Bore 11.375; Stroke 6.5
VSP5	0	1700		0000	C-126157			0	No	No	" / "	8.75 Bore; 6.5 Stroke
VSP7	0	1700		0000	C120992			0	No	No	" / "	Bore 11.375; Stroke 6.5
VSP8	0	1700		0000	C-121087			0	No	No	" / "	Bore 11.375; Stroke 6.5
VSP9	0	1700		0000	C-121083			0	No	No	" / "	Bore 11.375; Stroke 6.5
VSP10	0	1700		0000	C-120990			0	No	No	" / "	Bore 11.375; Stroke 6.5
VSP11	0	1700		0000	C-121088			0	No	No	" / "	8.75 Bore; 6.5 Stroke
VSP12	0	1700		0000	C-121089			0	No	No	" / "	
VSP13	0	1700		0000	C-121082			0	No	No	" / "	Bore 8.75; Stroke 6.5
VSP14	0	1700		0000	C-12090			0	No	No	" / "	Bore 8.75; Stroke 6.5
VSP15	0	1700		0000	C-120993			0	No	No	" / "	8.75 Bore; 6.5 Stroke
VSP16	0	1700		0000	C-121084			0	No	No	" / "	Bore 8.75; Stroke 6.5
VSP17	0	1700		0000	0			0	No	No	" / "	Bore 8.75; Stroke 6.5
VSP18	0	1700		0000	0			0	No	No	" / "	Bore 11.375; Stroke 6.5
VSP6	0	1700		0000	C-121081			0	No	No	" / "	
VRU1	0" x 13.3' x 6'	245		2004	15020101		19686			Yes	" / "	Skid dims 6'W x 13'4"L Vapor Recovery Unit
VRU2	0" x 8'	0		0	VRU50				No	Yes	" / "	
MS7P	0	1440		0	12108492						" / "	

**Separator Packages**

Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
-------------	------	----	--------------	------	----	----	----	-------	--------	------	--------	-----------------

**Plants**

Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
PL19	48" x 27.5' x 7'	1440		2003	HS8X11401-10		25200	0	No	Yes	" / "	7'W x 27'6"L and 10mm
PL40	42" x 8'	550		2008	1A177-01		4055				" / "	Reflux Accumulator Plant
PL8	36" x 8'	1250		2004	0404-002		460	0	No	Yes	" / "	Cold Separator
PL24P	24" x 29.5'	150		1979	80-43A				No	Yes	" / "	
PL28P	24" x 50'	1200		1984	1276						" / "	30 GPM Amine Plant
PL23	20" x 7.5'	720		1981	81-313						" / "	
PL2	0	1440		0000	0			0		Yes	" / "	5MMBTU JT Plant / (1) 4" Coils - 4'x20' / (1) 4" Coils, Insulated - 4'x23'
PL3	0	150		1985	1844			0		Yes	" / "	25-30 GPM Amine Plant
PL5P	0	1100		1984	0			0			" / "	5MM Refrig. / PNID available
PL6P	0	1440		0000	0			0		Yes	" / "	160 GPM Amine Unit
PL7	0	0		1953	0			0	Yes	Yes	" / "	JT Plant
PL9P	0	0		0000	0			0	Yes	No	" / "	
PL11P	0	0		1984	0			0	No	Yes	" / "	16 mm refrig plant
PL10P	0	0		0000	0			0	Yes	No	" / "	300 GPM Amine Plant

PL13	0" x 36' x 8'	0		0000	0			0	Yes	No	" / "	
PL15P	0	0		0000	0			0	Yes	No	" / "	100 GPM Amine Plant
PL16P	0	0		2011	0			0	No	No	" / "	90 GPM Amine Plant
E20P	0	1000		1996	618.1			0	No	Yes	" / "	Liquid Gas Separator/Chiller Exchanger
PL20P	0	1000		1996	018.2				No	Yes	" / "	Gas Exchanger Plant
PL21P	0	1345		2002	1016		16				" / "	
PL22P	0	450		0	T08L08412						" / "	Model# CDT0600L6D Part# 865 1MMSCF/day chiller Highside 450 lowside 178 has a 1250 PSIG cold Separator
PL25	0	1440		2010	D07295				No	Yes	" / "	Tower 10.75 packed 1440 700,000 mcf Reboiler 750M BTU/hr 10,000 flux rate KimRay Pumps w/Amine Kit
PL27	0" x 40' x 12'	1440		2007	3009		2291	3	Yes	Yes	" / "	80MM JT Plant
PL29	0	1100		1984	0						" / "	15mm-20mm Refrig that wasreconditioned in 2005
PL30P	0	0		0	0						" / "	15 mm Refrig
PL31P	0	0		0	0						" / "	15mm Refrig
PL33P	0	1440		2002	EL9F12202-01		D-99758				" / "	5mmscfd
PL35P	0	1440		2006	MM8T26401-03		36181				" / "	2mm
PL36P	0	1440		2004	EL9F57001-05		27971				" / "	3mm
PL37P	0	1440		2001	EL9E60703-01		19078				" / "	5mmscfd
PL42	0	0		0	0						" / "	300MM/day CRYO Plant
PL41	0	0		0	0						" / "	200 GPM Amine Plant

Propane Tanks												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
PT11P	94" x 39'	50		1962	109396-2				No		" / "	Gasoline Storage Tank
PT10	72" x 33.5'	250		1960	43062		43062				" / "	7500 Gallon Tank
PT3	30" x 5.5'	250		2005	9SG060687			0	No	Yes	" / "	
PT4	30" x 5'	250		2006	2SG074040			0	No	Yes	" / "	

Pumps												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
P64	8" x 6'	40		0000	143698			0	No	Yes	" / "	Amine Booster Pumps; Part of PL9
P19	0	0		0000	0			0			" / "	Triplex pump (no tag) / KP3300
P20	0	0		0000	0			0			" / "	Triplex pump / no tag / KP3300
P34	0	0		0000	P156B-37			0			" / "	Quintex Pump w/ 2.5" plungers
P54	0	0		0000	51203			0	No	Yes	" / "	model:3364-6F/plunger size:1.75/discharge:1480#
P55	0	0		0000	51202			0		Yes	" / "	model:3364-6F/plunger size:2/discharge:1390#/max RPM:500
P58	0	7500		0000	800012-2			0	No	Yes	" / "	

<a href="#">P59</a>	0	7500		0000	800012-1			0	No	Yes	" / "	
<a href="#">P60</a>	0	0		0000	KP998650S			0	No	Yes	" / "	
<a href="#">P66</a>	0	0		0000	0			0	No	Yes	" / "	Skid Size 10'Wx28'L; No tag; Triplex Pump Skid
<a href="#">P67</a>	0	0		0000	0			0	No	Yes	" / "	Triplex Pump Skid - Skid Size 10'Wx28'L
<a href="#">P68</a>	0	0		0000	22875			0	No	Yes	" / "	Skid Size 10'Wx28'L; Triplex Pump Skid; Model HR25
<a href="#">P70</a>	0	510		1998	98.01022.0122			0	No	Yes	" / "	8' x 7' 6" x 8' 6" - Triplex Pump Skid
<a href="#">P73P</a>	0	0		1981	0			0	No	Yes	" / "	7.517 Bore - Skid Size: 9' 7" L x 3' 9" W - HP 11311/HP250
<a href="#">P74P</a>	0	0		0000	HP11012			0	No	Yes	" / "	Skid Size 9' 7" L x 3' 9" W; Triple Plunger Pump HP250M
<a href="#">P76</a>	0" x 7' x 3'	0		2000	0				No	Yes	" / "	125M HP
<a href="#">P77</a>	0" x 7' x 3'	0		2000	0				No	Yes	" / "	125M HP Elektrim 230/460 volt motor
<a href="#">P78</a>	0	0		0	800985-501			0	No	Yes	" / "	1.625 x 2.25 suction pressure 200 discharge pressure 700 on skid with P79
<a href="#">P79</a>	0	0		0	800985-502				No	Yes	" / "	1.625 x 2.25 200 suction pressure 700 discharge pressure on skid with P78
<a href="#">P80</a>	0	0		2009	67520TL						" / "	3.5" stroke Rated Speed 440 Model 110Q-3M
<a href="#">P81</a>	0	0		0	67375TL						" / "	Stroke 3.5" Rated Speed 440 Model# 110Q-3M
<a href="#">P82</a>	0	0		0	63443TL						" / "	Plunger size 2" stroke 3.5" Rated Speed 440 Max discharge Pressure 1620 Model 110Q-3M
<a href="#">P83</a>	0	0		0	63445TL						" / "	Model # 110Q-311 Plunger size 2" Rated speed 440 Stroke 3.5 Max Discharge Pressure 1620
<a href="#">P85</a>	0	0		0	64088TL						" / "	Model# 110Q-3M Plunger size 2" Rated speed 440 Stroke 3.5 Max discharge pressure 1620
<a href="#">P86</a>	0	0		0	64090TL						" / "	Model# 110Q-3M Stroke 3.5 Rated speed 440 Max discharge Pressure 1620
<a href="#">P87</a>	0	0		2007	128011A						" / "	HP125
<a href="#">P88</a>	0	0		0	62486						" / "	Model 110Q-3LS Plunger size 2.75 Rated speed 440 stroke 3.5 Max discharge pressure 855
<a href="#">P89</a>	0	0		0	63444TL						" / "	Model# 110Q3M Plunger size 2 Rated speed 440 Stroke 3.5 Max discharge pressure 1620
<a href="#">P91</a>	0	0		2007	128011-B						" / "	HP125
<a href="#">P92</a>	0	0		2008	66219						" / "	Model # 1100-3M Plunger size 2 Stroke 3.5 Rated Speed 440 Max Discharge pressure 1620
<a href="#">P93</a>	0	0		2008	66220						" / "	Model# 1100-3M Plunger size 2" Stroke 3.5 Pressure 1620 Rated Speed 440
<a href="#">P94P</a>	0	309		2013	2976A-1/2						" / "	Suction Pressure 309 Discharge Pressure 325 Driver mfr by Baldor 4 identical pumps available
<a href="#">P95</a>	0	0		0	0						" / "	Model Donkey
<a href="#">P96</a>	0	0		0	0						" / "	450 Pump
<a href="#">P97</a>	0	0		0	0						" / "	450 Pump
<a href="#">P98</a>	0" x 15.5'	1480		1984	24218-2				No	No	" / "	
<a href="#">P99</a>	0" x 15.5'	1480		1984	24218-1				No	No	" / "	size 3 x 4 x 8

<a href="#">P100</a>	0" x 16' x 8'	0		0	0						" / "	Skid 8'W x 16'L Variable speed Pump No tag on Pump
<a href="#">P101</a>	0" x 24.75' x 6.9'	0		2007	CE84569						" / "	Pump Jack Skid Torque Master Oil well motor model TM04060WF SN# 1-007 Pump Frame 326T Model 03012EP36326T
<a href="#">P103P</a>	0	1500		2011	952211-3						" / "	Model 163Q -4M Plunger Size 2.5 Stroke 4.5 Rated Speed 390 Rated Discharge Pressure 1345 Wheatly Pump
<a href="#">P104P</a>	0	1500		2011	70223TL						" / "	Model 163Q -4M Plunger Size 2.5 Stroke 4.5 Rated Speed 390 Rated Discharge Pressure 1345 Wheatly Pump
<a href="#">P105P</a>	0	0		0	0						" / "	amine P-D Pumps for PL41P
<a href="#">P106P</a>	0	0		0	0						" / "	
<a href="#">P107P</a>	0	0		0	0						" / "	
<a href="#">P108P</a>	0	0		1969	0						" / "	
<a href="#">P109P</a>	0	0		1969	0						" / "	
<a href="#">P110P</a>	0	0		1969	0						" / "	
<a href="#">P111P</a>	0	0		1969	0						" / "	

Reboilers												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">R78P</a>	48" x 26.3'	0		2006	0			0	No	Yes	" / "	
<a href="#">R134P</a>	42" x 12'	0		2009	HT2374			0	No	Yes	" / "	
<a href="#">R187</a>	42" x 10'	0		2006	11105.1			0	No	Yes	" / "	
<a href="#">R220</a>	42" x 17'	1MM BTU		2005	6849				No	Yes	" / "	Stack, Still, and Flash Drum available
<a href="#">R22</a>	36" x 28.75'	1440		1996	96W0328		4681	0	Yes	No	" / "	Vertical Scrubber
<a href="#">R24</a>	36" x 10'	0		1987	29843			0	Yes	No	" / "	Vertical Scrubber
<a href="#">R58</a>	36" x 10'	0		1989	31642			0	No	Yes	" / "	
<a href="#">R59</a>	36" x 10'	0		1991	33071			0	No	Yes	" / "	
<a href="#">R109</a>	36" x 15'	0		1998	1816			0	No	Yes	" / "	
<a href="#">R117</a>	36" x 12'	0		2004	5281			0	No	Yes	" / "	
<a href="#">R118</a>	36" x 10'	0		2006	7774			0	No	Yes	" / "	
<a href="#">R120P</a>	36" x 25'	0		1984	GPT-9C21803-01			0	No	Yes	" / "	10 gpm Amine/Glymene Plant w/ T234
<a href="#">R124</a>	36" x 10'	750		0000	0			0	No	No	" / "	No tag
<a href="#">R153</a>	36" x 10'	0		1985	50196			0	No	Yes	" / "	
<a href="#">R159</a>	36" x 10'	0		1971	71-6510			0	No	Yes	" / "	Atmos working pressure
<a href="#">R161</a>	36" x 10'	0		2007	13858-1			0	No	Yes	" / "	
<a href="#">R162</a>	36" x 15'	15		1984	47860		8562	0	No	No	" / "	
<a href="#">R163</a>	36" x 15'	0		1987	29366			0	No	Yes	" / "	Charcoal
<a href="#">R176</a>	36" x 10'	0		1984	24632			0	No	Yes	" / "	Weight: 2550
<a href="#">R177P</a>	36" x 10'	0		1994	89730			0	No	No	" / "	GCP-500
<a href="#">R190</a>	36" x 10'	0		1976	28.068			0	No	Yes	" / "	
<a href="#">R184P</a>	36" x 10'	0		1994	89732				No	Yes	" / "	
<a href="#">R198</a>	36" x 10'	0		2010	9225				No	Yes	" / "	

<a href="#">R205</a>	36" x 10'	0		2010	9175				No	Yes	" / "	
<a href="#">R208</a>	36" x 15'	0		2009	8922				No	Yes	" / "	
<a href="#">R207</a>	36" x 15'	0		2000	C-488775001				No	Yes	" / "	
<a href="#">R210</a>	36" x 15'	0		2009	8920				No	Yes	" / "	
<a href="#">R209</a>	36" x 15'	0		2009	8862				No	Yes	" / "	
<a href="#">R215</a>	36" x 15'	0		2009	8970						" / "	
<a href="#">R86</a>	30" x 10'	0		1996	520			0	No	Yes	" / "	
<a href="#">R85</a>	30" x 10'	0		2000	2426			0	No	Yes	" / "	375M BTU
<a href="#">R94</a>	30" x 20'	0		0000	0			0	No	Yes	" / "	no tag
<a href="#">R107</a>	30" x 18.5'	0		0000	0			0	No	Yes	" / "	Repaired by K.W. International 2006
<a href="#">R108</a>	30" x 10'	0		2006	7313			0	No	Yes	" / "	No stack or steel column
<a href="#">R125</a>	30" x 10'	0		1996	515			0	No	Yes	" / "	Real Good Unit
<a href="#">R126</a>	30" x 10'	0		1980	16577			0	No	Yes	" / "	
<a href="#">R132</a>	30" x 10'	0		1984	RG-373			0	No	Yes	" / "	
<a href="#">R131</a>	30" x 10.75'	0		1982	RG244			0	No	Yes	" / "	
<a href="#">R135</a>	30" x 10'	0		1997	1422			0	No	Yes	" / "	
<a href="#">R133</a>	30" x 15'	5		1986	2846-01A			0	No	No	" / "	
<a href="#">R156</a>	30" x 10'	0		1988	30423			0	No	Yes	" / "	
<a href="#">R151</a>	30" x 10'	0		1990	32345			0	No	Yes	" / "	
<a href="#">R164</a>	30" x 10'	0		1980	17559			0	No	Yes	" / "	
<a href="#">R158</a>	30" x 8'	125		1983	83-D6139-01		1029		No	Yes	" / "	
<a href="#">R181</a>	30" x 10'	0		2005	6616						" / "	
<a href="#">R213</a>	30" x 12.5'	0		1984	T-4258206-02				No	Yes	" / "	
<a href="#">R71</a>	24" x 8.3'	0		1989	HL-1X54604-01			0	No	Yes	" / "	
<a href="#">R89</a>	24" x 8'	0		1982	HLT9A903 01 26			0	No	Yes	" / "	
<a href="#">R90</a>	24" x 7.5'	0		1996	92399			0	No	Yes	" / "	
<a href="#">R128</a>	24" x 6'	0		0000	NO-9008			0	No	Yes	" / "	
<a href="#">R141</a>	24" x 6'	0		0000	23877			0	No	Yes	" / "	Glycol Reboiler
<a href="#">R143</a>	24" x 8.5'	0		2004	RS183204			0	No	Yes	" / "	
<a href="#">R140</a>	24" x 7.5'	0		0000	RG307705			0	No	Yes	" / "	
<a href="#">R145</a>	24" x 7.5'	0		2003	VS102-103			0	No	Yes	" / "	
<a href="#">R165</a>	24" x 8'	0		2005	1001-404			0	No	Yes	" / "	
<a href="#">R173</a>	24" x 10'	0		1997	EL8D26401-01			0	No	Yes	" / "	
<a href="#">R191</a>	24" x 15'	5		2005	EL9F99201-05			0	No	Yes	" / "	
<a href="#">R202</a>	24" x 10'	1200		2006	10095-2				No	Yes	" / "	
<a href="#">R226P</a>	24" x 23'	375 BTU		1983	6888-03						" / "	Amine Reboiler
<a href="#">R33</a>	20" x 6'	0		2005	BN471C			0	No	No	" / "	Aplex Pump (Duplex)
<a href="#">R68</a>	20" x 9'	0		1989	31466			0	No	Yes	" / "	200k BTU
<a href="#">R99</a>	20" x 7.8'	0		1982	HLT9A734-01-13			0	No	Yes	" / "	w/ stack and steel column
<a href="#">R110</a>	20" x 5.25'	0		1977	12386			0	No	Yes	" / "	Sock filter
<a href="#">R111</a>	20" x 9'	0		1984	24823			0	No	Yes	" / "	
<a href="#">R112</a>	20" x 6'	0		1983	2.2.995			0	No	Yes	" / "	1-40 Kinray Pump

R122	20" x 9'	0		2006	11497			0	No	Yes	" / "	
R130	20" x 6'	0		2001	3807			0	No	Yes	" / "	
R142	20" x 6'	0		0000	24408			0	No	Yes	" / "	Glycol Reboiler
R152	20" x 9'	0		0000	?040214			0	No	Yes	" / "	LJ038
R167	20" x 6'	0		2008	GCR1101			0	No	Yes	" / "	
R169	20" x 5'	0		1990	31903			0	No	Yes	" / "	With stack & still column
R170	20" x 8.5'	5		2009	007467-3			0	No	Yes	" / "	Has stack and still column
R171	20" x 8.5'	5		2010	007467-7			0	No	Yes	" / "	With stack & still column
R172	20" x 6'	0		1977	12390			0	No	Yes	" / "	
R174	20" x 9'	0		2004	5949			0	No	Yes	" / "	
R175P	20" x 9'	0		1980	18443			0	No	Yes	" / "	1200 lbs./Glycol Reboiler
R178	20" x 5'	0		2004	5153			0	No	No	" / "	
R188	20" x 6'	0		1998	1819			0	No	Yes	" / "	
R196	20" x 9'	0		1981	9A25803-02			0	No	Yes	" / "	
R194	20" x 6'	0		1980	18433			0	No	Yes	" / "	
R197	20" x 6'	0		2001	3211				No	Yes	" / "	
R203	20" x 6'	0		1988	4391						" / "	
R183	20" x 5'	0		0	10394						" / "	
R206	20" x 6'	0		0	0						" / "	
R212	20" x 9'	0		2003	4812						" / "	
R219P	20" x 16'	0		0	RG-598-1208						" / "	
R80	18" x 6.5'	0		1973	T3010302-01			0	No	Yes	" / "	
R91	18" x 5.75'	0		1989	89-503-01			0	No	Yes	" / "	
R105	18" x 5'	125		2007	112560			0	No	Yes	" / "	
R106	18" x 5'	125		2007	112561			0	No	Yes	" / "	
R113	18" x 5'	0		2001	100190			0	No	No	" / "	
R123	18" x 9'	0		1971	RG-189-2465			0	Yes	Yes	" / "	
R127	18" x 5'	0		0000	0			0	No	Yes	" / "	No tag
R129	18" x 9'	0		1980	T-9745201-03			0	No	Yes	" / "	
R189	18" x 6.5'	0		1977	T6295701			0	No	Yes	" / "	
R217P	18" x 9.5'	0		2008	EL9G75901-01						" / "	
R218P	18" x 9.5'	0		2008	MM9M39701-02						" / "	
R100	16" x 4'	0		0000	F13303			0	No	No	" / "	
R147	16" x 7'	0		1980	HLT 94528 01 04			0	No	Yes	" / "	Charcoal
R195	16" x 10'	0		1989	31564			0	No	Yes	" / "	
R104	12" x 3.83'	0		0000	0			0			" / "	no tag
R146	12" x 4'	0		2003	0			0	No	Yes	" / "	
R199	10" x 17.5'	5		2008	EL8131701-01						" / "	two Kimray 210 Pumps and an electric
R17	0	0		0000	0			0	Yes	No	" / "	
R21	0	0		1973	73-8277			0	Yes	No	" / "	
R43	0	0		1977	77A 3505			0	No	Yes	" / "	
R61	0	0		1998	1545			0	No	Yes	" / "	

R70	0	0		0000	0			0		Yes	" / "	
R76	0	0		1974	74-8927			0	No	Yes	" / "	scrapped coils
R77	0	0		0000	0			0		Yes	" / "	no tag / scrapped coils
R102	0	0		1982	495			0			" / "	
R137	0	0		2009	1001-1127			0	No	Yes	" / "	ATMos psi
R221P	0	250 BTU		2007	mmam0941-02						" / "	Glycol Reboiler Surge
R222P	0	375 BTU		1979	15757						" / "	Glycol Reboiler Skid
R223P	0	375 BTU		0000	N/A						" / "	
R224P	0	250 BTU		2003	EL9f2ff02-03						" / "	
R225P	0	200 BTU		1981	T-97957501-10						" / "	

Tanks												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
TK2	144" x 20'	0		0000	0			0			" / "	400 BBL tank
TK8	144" x 12'	0		1991	32767			0	Yes	No	" / "	
TK29	144" x 15'	16		2000	32235				Yes	No	" / "	300 BBL tank
TK30	144" x 15'	0		2009	3156-09				Yes	No	" / "	Heavy Plastic 300 BBL tank.
TK31	144" x 15'	16		1994	26124				Yes	No	" / "	300 BBL Tank
TK27	120" x 15'	0		2013	1001-2061			0	Yes	No	" / "	210 Gallons
MST2-110	48" x 4' x 48"	0		2009	0			0	No	No	" / "	48" x 4' x 10'
ST1	48" x 4' x 6'	0		2006	7831			0	Yes	No	" / "	
ST10	48" x 4' x 6'	1 atmos		2005	6713			0	Yes	No	" / "	
ST4	48" x 4' x 6'	0		0000	0			0	Yes	No	" / "	
ST25	48" x 6' x 4'	0		2012	1001-1929			0	No	No	" / "	4'W x 6'L x 4'H
ST26	48" x 6' x 4'	0		2013	1001-2308			0	No	No	" / "	4'W x 6'L x 4'H
ST29A	48" x 10'	0		2006	7731				Yes	No	" / "	
TK12	44" x 4'	0		0000	1-07-00470			0	Yes	Yes	" / "	300 gallon poly tank w/ stand / no tag
TK19	14" x 15.5'	0		0000	0			0	Yes	No	" / "	
ST21	4" x 6'	0		2008	3039			0	No	No	" / "	
TK5	0	0		0000	0			0			" / "	400 bbl tank
ST15	0" x 4' x 10'	0		2003	32006885			0	No	Yes	" / "	
ST14	0" x 4' x 10'	0		0000	0			0			" / "	
ST18	0	0		0000	0			0			" / "	no tag; 4'x4'x4'
ST19	0	0		0000	0			0			" / "	no tag; 8'x4'x4'
TK22P	0	0		0000	0			0	No	No	" / "	400 Barrel; Flowback Tank
TK24	0	0		2003	3065			0	No	No	" / "	100 BBL; ABJ-3200 Surge Tank
ST28	0" x 72' x 4"	0		2001	3470				Yes	No	" / "	
ST29	0" x 10'	0		2006	7865				No	No	" / "	



Thermal Oxidizers												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info

Ready-to-Go/Field Ready												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">H804P</a>	96.75" x 20'	108		1958	H-1954-58						" / "	
<a href="#">V903P</a>	96" x 14'	0		1969	9242						" / "	
<a href="#">V904P</a>	96" x 14'	0		1969	0						" / "	
<a href="#">V905P</a>	96" x 14'	0		1969	0						" / "	
<a href="#">T363P</a>	78" x 55'	1440		2001	01141101				Yes	No	" / "	
<a href="#">C26</a>	74.5" x 3.25'	150		2012	12763101-1		73688	0	No	No	" / "	Model No.: 3614
<a href="#">V711P</a>	72" x 15'	1440		2002	64097-1			3	Yes	No	" / "	
<a href="#">H803P</a>	72" x 14.6'	1205		1967	7888		4591				" / "	PL41
<a href="#">T391P</a>	72" x 59.6'	1205		1967	7890		4593				" / "	
<a href="#">H802P</a>	66" x 12'	97		1967	0						" / "	Flare KO Drum
<a href="#">H805P</a>	66" x 20'	200		1980	9187		1635				" / "	part of PL41P amine flash tank
<a href="#">BT20</a>	60" x 4'	0		2006	11497			0	No	Yes	" / "	
<a href="#">V737</a>	60" x 20'	1100		0000	9046		3181	0	Yes	No	" / "	
<a href="#">V736</a>	60" x 20'	1100		0000	9047		3182	0	Yes	No	" / "	
<a href="#">H717</a>	60" x 10'	1350		2001	AC-087		3610		Yes	No	" / "	
<a href="#">LH004-15</a>	60" x 20'	0		1982	T-1337001-01				No	Yes	" / "	Trailer Vin # 624253
<a href="#">V896P</a>	60" x 71'	75		1969	96596						" / "	
<a href="#">H548</a>	48" x 15'	125		1995	95-452		24738	3	Yes	Yes	" / "	Water Skimmer; Ready to Go
<a href="#">H646</a>	48" x 15'	1440		1998	668-A		64	0	No	No	" / "	
<a href="#">H686P</a>	48" x 15'	1440		0000	0			0	Yes	Yes	" / "	
<a href="#">ST25</a>	48" x 6' x 4'	0		2012	1001-1929			0	No	No	" / "	4'W x 6'L x 4'H
<a href="#">ST26</a>	48" x 6' x 4'	0		2013	1001-2308			0	No	No	" / "	4'W x 6'L x 4'H
<a href="#">LH002-14</a>	48" x 17.5'	0		1987	298573			0		Yes	" / "	Trailer mounted rental unit Trailer Vin # 624277
<a href="#">LH178</a>	48" x 17.5'	0		2001	3276				No	Yes	" / "	
<a href="#">LH003-15</a>	48" x 17.5'	0		2005	6815						" / "	Trailer Vin # 624278
<a href="#">H794</a>	48" x 15'	1400		2013	CLB13-47		46626		No	Yes	" / "	
<a href="#">V873P</a>	48" x 10'	285		2012	12-3417			3	No	No	" / "	3-Phase Separator
<a href="#">V874P</a>	48" x 10'	285		2012	12-4357			3	No	No	" / "	3-Phase Separator
<a href="#">V875P</a>	48" x 10'	285		2012	12-4355		2972	3	No	No	" / "	3-Phase Separator
<a href="#">V877P</a>	48" x 10'	285		2012	12-4354			3	No	No	" / "	3-Phase Separator
<a href="#">V878P</a>	48" x 10'	285		2012	12-4352			3	No	No	" / "	3-Phase Separator
<a href="#">V879P</a>	48" x 10'	285		2012	12-4349			3	No	No	" / "	3-Phase Separator
<a href="#">V880P</a>	48" x 10'	285		2012	12-4351			3	No	No	" / "	3-Phase Separator
<a href="#">V876P</a>	48" x 10'	285		2012	12-3664			3	No	No	" / "	3-Phase Separator
<a href="#">V901P</a>	48" x 10'	285		2012	12-4348						" / "	

<a href="#">V902P</a>	48" x 10'	285		2012	12-3665						" / "	
<a href="#">V899P</a>	48" x 10'	285		2012	12-4356						" / "	
<a href="#">v900P</a>	48" x 10'	285		2012	12-3416						" / "	
<a href="#">H537</a>	42" x 15'	1440		2007	CL07-836	37276	2	No	No	" / "	Repaired by KW International in 2009	
<a href="#">WTP001-14</a>	42" x 10'	1440		2014	GPT-1M21502-01	5315				" / "		
<a href="#">WTP002-14</a>	42" x 10'	1440		2014	GPT-1G03502-01					" / "		
<a href="#">WTP003-14</a>	42" x 10'	1440		2014	GPT-1J42502-01					" / "		
<a href="#">WTP004-14</a>	42" x 10'	1440		2014	0					" / "		
<a href="#">WTP005-14</a>	42" x 10'	1440		2014	0					" / "		
<a href="#">H793P</a>	42" x 12.6'	740		1993	120593					" / "	Pressure Vessel	
<a href="#">H513</a>	36" x 10'	1440		2005	60004245	584	3	No	Yes	" / "		
<a href="#">ES105</a>	36" x 15'	1440		1980	T-732 5517-01		0	Yes	Yes	" / "	Filter Separator - Horizontal	
<a href="#">H701</a>	36" x 10'	1440		2007	2876		2	Yes	No	" / "	Repaired by DBI Welding on 9/5/13	
<a href="#">T309</a>	36" x 35'	1440		2008	113752					" / "		
<a href="#">V745</a>	36" x 10'	125		2007	06931	36325	2			" / "		
<a href="#">ES153</a>	36" x 10'	1300		2006	06-531	35973		No	No	" / "		
<a href="#">H763P</a>	36" x 10'	1440		2012	1206-01	35	3			" / "		
<a href="#">H764P</a>	36" x 10'	1440		2012	1108-02	26	3			" / "	Trailer Mounted	
<a href="#">T101P</a>	30" x 25'	1440		2005	05-302	34949	0	No	No	" / "	wt: 11800 lbs./ abs scrubber 8 tray tower	
<a href="#">GU3</a>	30" x 6'	0		0000	0		0	No	Yes	" / "	no tag	
<a href="#">FS80</a>	30" x 12.5'	720		2011	CL11-1620	42929	0	Yes	No	" / "	Ready to Go	
<a href="#">FS143</a>	30" x 12.5'	1440		2000	00-176	29773		No	Yes	" / "		
<a href="#">FS137P</a>	30" x 15'	1395		2008	03490-3	2635		No	No	" / "		
<a href="#">V840</a>	30" x 10'	1440		2011	W6168	5844	2	Yes	No	" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.	
<a href="#">V841</a>	30" x 10'	1440		2011	W7275	6923		Yes	No	" / "	vertical 2 phase separator with 4" in and out NB registered and 8" clean outs.	
<a href="#">V842</a>	30" x 10'	1440		2011	W6153	5842		Yes	No	" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.	
<a href="#">V843</a>	30" x 10'	1440		2011	W6234	5953		Yes	No	" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.	
<a href="#">V844</a>	30" x 10'	1440		2011	W7276	6924				" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.	
<a href="#">V845</a>	30" x 10'	1440		2011	W5152	5795		No		" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.	

<a href="#">V846</a>	30" x 10'	1440		2011	W7273		6926		No		" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V848</a>	30" x 10'	1440		2011	W6657		6847		No		" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V854</a>	30" x 10'	1440		2011	W6175		5783				" / "	
<a href="#">V895P</a>	30" x 8'	144		1969	9209		5597				" / "	
<a href="#">V898P</a>	27.5" x 33.5'	180		1999	25349-2						" / "	amine charcoal filter part of PL41P
<a href="#">FS56P</a>	24" x 12.5'	1440		1984	84-871		15977	0	No	No	" / "	
<a href="#">H445</a>	24" x 10'	1440		2000	00-316		30019	2	No	No	" / "	
<a href="#">E10</a>	24" x 40'	1200		2001	5010		712	0	No	No	" / "	National Gas C
<a href="#">V763</a>	24" x 6'	200		1973	T3200003-01				No	Yes	" / "	
<a href="#">T346</a>	24" x 30'	1440		2010	CL09-913				No	Yes	" / "	Packed Tower
<a href="#">V910</a>	24" x 7.6'	1440		1999	99-687			3			" / "	
<a href="#">V908</a>	24" x 7.6'	1440		1997	97-1038		27077				" / "	
<a href="#">V906</a>	24" x 10'	1440		1997	87-200			2			" / "	
<a href="#">FS141</a>	20" x 14'	211		1975	12293		7407		No	No	" / "	Model 75H-8-FG372A
<a href="#">FS144</a>	20" x 12'	1440		2009	S9022		1105		No	No	" / "	
<a href="#">FS145</a>	20" x 12'	1440		2008	508-75		724		No	No	" / "	
<a href="#">FS147</a>	20" x 12'	1440		2008	508-77		726		No	No	" / "	
<a href="#">FS148</a>	20" x 12'	1440		2007	V5838		1032		No	Yes	" / "	
<a href="#">V909</a>	20" x 706'	1440		2007	P2354		1354	3			" / "	
<a href="#">V857</a>	16" x 7.6'	1440		2005	4371			2,000			" / "	Non code
<a href="#">V858</a>	16" x 7.6'	1400		2005	4373			2	No	No	" / "	Non code
<a href="#">V859</a>	16" x 7.6'	1440		2005	4193			2	No	No	" / "	missing tag Non code
<a href="#">V860</a>	16" x 7.6'	1440		2005	4136			2	No	No	" / "	Non code
<a href="#">V861</a>	16" x 7.6'	1440		2006	2575				No	No	" / "	Non code
<a href="#">V862</a>	16" x 7.6'	1440		2005	4339			2	No	No	" / "	Non code
<a href="#">V863</a>	16" x 7.6'	1440		2005	4191			2	No	No	" / "	Non code
<a href="#">V864</a>	16" x 7.6'	1440		2006	5014			2	No	No	" / "	Non code Manufacturer-Whitehead Production Equipment
<a href="#">E24P</a>	15" x 26.875'	175		2013	0						" / "	Regen Gas Heater 1044 square feet Tube side design test pressure 1135 Tube side inlet/outlet 4" 600 Shell side inlet/outlet 3" 600
<a href="#">T190</a>	12.75" x 15'	1440		1977	22287			0	No	No	" / "	repaired by: Facilities 2012
<a href="#">FS123</a>	12.75" x 4.25'	150		2008	E8697401-08		4G080	0	No	No	" / "	Vertical
<a href="#">T189</a>	12" x 15'	125		1983	0			0	No	No	" / "	
<a href="#">ES175</a>	10.75" x 8'	1440		2010	P2975		1975				" / "	
<a href="#">T187</a>	8.625" x 14'	1440		2009	0			0	No	No	" / "	

<a href="#">H727</a>	8.625" x 12'	1000		2013	1001-2321			0	No	No	" / "	Horizontal Volume Bottle
<a href="#">ES174</a>	8.625" x 7.6'	1440		2005	V05-593		2248				" / "	
<a href="#">H801P</a>	6.6" x 24'	50		1970	9374						" / "	Flare Gas/Liquid Sep
<a href="#">R137</a>	0	0		2009	1001-1127			0	No	Yes	" / "	ATMos psi
<a href="#">MS1P</a>	0	0		2008	0			0	No	Yes	" / "	Sensus 12" AAT-230 meter; Low pressure high volume application; Pressure reducing skid
<a href="#">GC18P</a>	0	0		2013	C2330495-01						" / "	Model # LMC-311F
<a href="#">BT30</a>	0" x 6.5'	0		0	0				No	No	" / "	5'7" W x 6'6"lg x 13'9"T
<a href="#">P103P</a>	0	1500		2011	952211-3						" / "	Model 163Q -4M Plunger Size 2.5 Stroke 4.5 Rated Speed 390 Rated Discharge Pressure 1345 Wheatly Pump
<a href="#">P104P</a>	0	1500		2011	70223TL						" / "	Model 163Q -4M Plunger Size 2.5 Stroke 4.5 Rated Speed 390 Rated Discharge Pressure 1345 Wheatly Pump
<a href="#">MS7P</a>	0	1440		0	12108492						" / "	
<a href="#">G19P</a>	0	0		2006	OLY00000LNGT00419			480 3ph			" / "	
<a href="#">E33P</a>	0	13.403 MBTU/HR		1969	6632-1						" / "	
<a href="#">V897P</a>	0	0		0	0						" / "	Hot Oil Filter
<a href="#">FS173P</a>	0	0		2005	05w0049						" / "	
<a href="#">E34P</a>	0	75		1969	S-15899						" / "	
<a href="#">P106P</a>	0	0		0	0						" / "	
<a href="#">P107P</a>	0	0		0	0						" / "	
<a href="#">P108P</a>	0	0		1969	0						" / "	
<a href="#">P109P</a>	0	0		1969	0						" / "	
<a href="#">P110P</a>	0	0		1969	0						" / "	
<a href="#">P111P</a>	0	0		1969	0						" / "	
<a href="#">C70P</a>	0	75		1969	69-15-20						" / "	Cooler for PL41p
<a href="#">C71P</a>	0	500		0	0						" / "	
<a href="#">E36P</a>	0	0		1969	6632-2						" / "	
<a href="#">HT56P</a>	0	0		0	0						" / "	
<a href="#">HT55P</a>	0	0		0	0						" / "	
<a href="#">V907</a>	0	1440		1980	T-7325516-01						" / "	

Vertical Vessels												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">V489</a>	144" x 22'	120		1976	21396			0	Yes	No	" / "	repaired by: CO. Pagwell Brothers Inc 1989

<a href="#">V703P</a>	126" x 18.25'	34		1975	9595		2023	0	No	No	" / "	CO-2 Stripper Reflux Drum
<a href="#">V702P</a>	126" x 18.25'	34		1975	9577		2008	0	No	No	" / "	CO-2 Stripper Reflux Drum
<a href="#">V581</a>	120" x 17.5'	150		1976	76-A-2851			0	Yes	No	" / "	Flare Scrubber/Fuel Gas Scrubber
<a href="#">V831P</a>	120" x 33'	150		1993	2188		463				" / "	Oxygen Stripper Tower
<a href="#">V684P</a>	110" x 19.75'	1312		2004	20020A			0	Yes	No	" / "	Purchaser's Serial # (Equipment #) P1-MBF-66130
<a href="#">V683P</a>	110" x 19.75'	1312		2004	20020A			0	No	No	" / "	Purchaser's Serial # (Equipment #) P1-MBF-66130
<a href="#">V869P</a>	102" x 15'	98		2000	25194		384				" / "	Storage Tank
<a href="#">V730</a>	96" x 10'	100		2008	5922-004		3	3	Yes	No	" / "	Condensate Surge Tank
<a href="#">V903P</a>	96" x 14'	0		1969	9242						" / "	
<a href="#">V904P</a>	96" x 14'	0		1969	0						" / "	
<a href="#">V905P</a>	96" x 14'	0		1969	0						" / "	
<a href="#">V884P</a>	90" x 10'	1206		1970	174443						" / "	
<a href="#">V396</a>	84" x 15'	1440		1975	T4083205-01			0			" / "	
<a href="#">T219P</a>	84" x 38'	1250		1983	100228-01-1		54152	0	Yes	No	" / "	
<a href="#">V637</a>	84" x 10'	125		2001	60001058		52	2	Yes	No	" / "	
<a href="#">V868P</a>	84" x 25'	1440		2000	9691-1		113				" / "	
<a href="#">V883P</a>	84" x 12'	1110		1978	7001-49-16-1		416				" / "	Inlet Gas Sep
<a href="#">V631</a>	78" x 16'	250		1963	S3912			0	Yes	No	" / "	Amine Surge Tank; Part of PL9; Repaired by Alter Rama in 1999
<a href="#">V288</a>	72" x 15'	200		1990	9049302			0	Yes	No	" / "	
<a href="#">V490</a>	72" x 32'	128		1972	N-9421			0	Yes	No	" / "	w/ ladders
<a href="#">V491</a>	72" x 32'	128		1972	N-9420			0	Yes	No	" / "	
<a href="#">V543</a>	72" x 20'	125		1973	73-8013-A			0	Yes	Yes	" / "	Repaired by Coastline Process in 1993
<a href="#">V616</a>	72" x 9'	75		1971	250621			0	Yes	No	" / "	Amine Reflux Accumulator; Part of PL9; Repaired by RAMA in 1999
<a href="#">V711P</a>	72" x 15'	1440		2002	64097-1			3	Yes	No	" / "	
<a href="#">V726</a>	72" x 12'	150		1998	2620		1559	0	Yes	Yes	" / "	
<a href="#">V764</a>	72" x 10'	715		1993	33692		20123		Yes	No	" / "	
<a href="#">V783</a>	72" x 20'	805		1967	54806-01-0		1707		Yes	No	" / "	Repaired by Atlas Products 2007 SN 2479 Hydrogen Sulfide Removal/ Desiccant Absorber
<a href="#">V832</a>	72" x 10'	283		2005	04-898		35000	2	No	Yes	" / "	Vent Scrubber
<a href="#">V385</a>	66" x 5'	1476		2001	CM2E760A03-01		21975	0	Yes	No	" / "	24" whirly scrub
<a href="#">V651</a>	66" x 10'	150		1990	K89 782		2329	0	Yes	No	" / "	Vessel Tag#MBF108/Vent Scrubber
<a href="#">V780</a>	66" x 12'	1011		1985	N-11659		C.A.0625	2	Yes	No	" / "	
<a href="#">V891P</a>	66" x 15'	1207		1970	9693		6018				" / "	Inlet Sep
<a href="#">V892P</a>	66" x 9.1'	1205		1969	9397						" / "	Inlet
<a href="#">T59</a>	60" x 24'	1000		1973	23576		62	0	Yes	No	" / "	
<a href="#">V294</a>	60" x 10'	100		1993	K-93-377		2841	0	Yes	No	" / "	vent scrubber
<a href="#">V372</a>	60" x 25'	1440		1995	PNPD360480		3112	0	Yes	No	" / "	Glycol Contactor
<a href="#">V408</a>	60" x 8'	1000		1970	K-150			0	Yes	No	" / "	

<a href="#">V493</a>	60" x 28'	1007		1981	2056-B			0	Yes	No	" / "	repaired by: S.W.G. 2000
<a href="#">V505</a>	60" x 8'	250		1995	2516	1223		3	Yes	No	" / "	Scrubber
<a href="#">V514</a>	60" x 10'	283		2004	03-666	33456		2	No	No	" / "	Vent Scrubber
<a href="#">V516</a>	60" x 10'	125		2000	3485.02C	264		0	No	No	" / "	
<a href="#">V520</a>	60" x 8'	125		1977	9226-1	814		0	Yes	No	" / "	Repaired by Universal Equipment in 2005
<a href="#">V628</a>	60" x 8'	100		1980	0	671		0	No	No	" / "	Vertical; Part of PL9
<a href="#">V716</a>	60" x 10'	125		1971	0			0	Yes	No	" / "	1st Stage Scrubber
<a href="#">V737</a>	60" x 20'	1100		0000	9046	3181		0	Yes	No	" / "	
<a href="#">V736</a>	60" x 20'	1100		0000	9047	3182		0	Yes	No	" / "	
<a href="#">V881P</a>	60" x 20'	1100		1978	T-6707701-01						" / "	
<a href="#">V896P</a>	60" x 71'	75		1969	96596						" / "	
<a href="#">V168</a>	54" x 15'	1440		1976	A2853			2	Yes	No	" / "	
<a href="#">V373</a>	54" x 12'	2000		1995	H02402-01	382		2	Yes	No	" / "	
<a href="#">T169</a>	54" x 24'	1480		1990	90-14	19-998		0	Yes	No	" / "	wt: 53,500
<a href="#">V674</a>	54" x 10'	150		1990	K89-781	2345		3	Yes	No	" / "	
<a href="#">V694</a>	54" x 20'	230		2002	1030			0	No	Yes	" / "	Flare Scrubber 10 feet tall
<a href="#">V740P</a>	54" x 14.33'	720		1960	330132			0	Yes	No	" / "	
<a href="#">V770</a>	54" x 10'	720		1976	76-392	5306		2	Yes	No	" / "	
<a href="#">V773</a>	54" x 9.7'	2160		1962	62-104			2	Yes	No	" / "	
<a href="#">MV56-161</a>	48" x 10'	125		1970	70-5140			0	Yes	No	" / "	no code stamp / repaired by: TYSCO 1990
<a href="#">V100</a>	48" x 8'	275		1984	GPT-1J89202-01			0	Yes	No	" / "	int. scrubber
<a href="#">V204</a>	48" x 15'	1200		1958	134260-58			0	Yes	No	" / "	
<a href="#">V238</a>	48" x 10'	125		2001	201137			0	Yes	No	" / "	glycol accumulator
<a href="#">V337</a>	48" x 10'	150		1975	GPT-433794101			0	No	No	" / "	
<a href="#">V392</a>	48" x 10'	1000		1980	0028-4			0	Yes	No	" / "	
<a href="#">V424</a>	48" x 12.5'	1440		1981	62184			0	Yes	No	" / "	
<a href="#">V502</a>	48" x 15'	125		1983	1938A			3	Yes	No	" / "	
<a href="#">V515</a>	48" x 10'	427		1970	1808			0	Yes	No	" / "	Scrubber
<a href="#">V518</a>	48" x 15'	1440		1975	12069			0	Yes	No	" / "	Missing Exchanger
<a href="#">V530</a>	48" x 10'	1200		1967	420005			0	No	No	" / "	Repaired by Universal Equipment in 1989
<a href="#">V582P</a>	48" x 8'	300		2006	1889	1758		0	Yes	No	" / "	wt: 5,700 // Stainless Steel Vessel
<a href="#">V583P</a>	48" x 8'	300		2007	1889	1758		0	Yes	No	" / "	wt: 5,100 CO2 removal gas cooler scrubber
<a href="#">V856</a>	48" x 5.5'	720		1978	S-468			0	Yes	No	" / "	Cyclone Scrubber
<a href="#">V855</a>	48" x 5.5'	720		1978	S-431			0	Yes	No	" / "	Cyclone Scrubber
<a href="#">V680</a>	48" x 10'	300		0000	813690	10976		0	No	No	" / "	
<a href="#">V697</a>	48" x 10'	1480		1989	K-89-537	2286		3	Yes	Yes	" / "	Repaired by MI Companies - 12/1/01
<a href="#">V771</a>	48" x 10'	2160		1962	62-105				Yes	No	" / "	
<a href="#">V825</a>	48" x 10'	150		1982	82D58570F				No	No	" / "	
<a href="#">V828</a>	48" x 16'	1100		2000	V402-592			3	No	No	" / "	

V839	48" x 10'	1440		2003	03-335		33155	3	No	Yes	" / "	
V873P	48" x 10'	285		2012	12-3417			3	No	No	" / "	3-Phase Separator
V874P	48" x 10'	285		2012	12-4357			3	No	No	" / "	3-Phase Separator
V875P	48" x 10'	285		2012	12-4355		2972	3	No	No	" / "	3-Phase Separator
V877P	48" x 10'	285		2012	12-4354			3	No	No	" / "	3-Phase Separator
V878P	48" x 10'	285		2012	12-4352			3	No	No	" / "	3-Phase Separator
V879P	48" x 10'	285		2012	12-4349			3	No	No	" / "	3-Phase Separator
V880P	48" x 10'	285		2012	12-4351			3	No	No	" / "	3-Phase Separator
V876P	48" x 10'	285		2012	12-3664			3	No	No	" / "	3-Phase Separator
V901P	48" x 10'	285		2012	12-4348						" / "	
V902P	48" x 10'	285		2012	12-3665						" / "	
V899P	48" x 10'	285		2012	12-4356						" / "	
v900P	48" x 10'	285		2012	12-3416						" / "	
V685	45" x 4'	1440		1966	133424601		15923	0	No	Yes	" / "	Vertical Accumulator; Repaired by General Fabricators, Inc. in 1999
V162	42" x 12'	1440		1983	N11450			0	Yes	No	" / "	
V169	42" x 15'	1440		1978	9326-1		875	0	Yes	No	" / "	
V242	42" x 13'	1440		1980	80-124		1452	0	Yes		" / "	test separator
V255P	42" x 10'	125		1988	88-09C			2	No	No	" / "	
V272	42" x 10'	1480		1988	FT-3112-1		3094	2	No	No	" / "	2nd stage suction scrubber
V336	42" x 12'	1480		1990	K-90-307		2409	0	Yes	No	" / "	vertical gas test separator
V359	42" x 10'	125		1984	84-1290C		16396	2	No	No	" / "	wt: 2240lbs
V384	42" x 12.5'	2000		1995	N12D02702-01		10545	3	Yes	No	" / "	
V386	42" x 5.5'	1475		2001	CM2E760B03-01		21974	0	Yes	No	" / "	12" whirly scrub
V421	42" x 10'	125		1975	75-A-1189			0			" / "	flare scrubber
V471	42" x 12'	1440		1982	46		46	3	Yes	No	" / "	
V517	42" x 15'	1440		1975	T-4083207-01			0	Yes	No	" / "	
V568	42" x 15'	1440		1976	1875			0	No	No	" / "	Scrubber
V578	42" x 10'	1440		1980	T-751990-01			3	No	No	" / "	
V588	42" x 8'	245		1989	B10702-01			0	Yes	No	" / "	
V587	42" x 8'	245		1989	B10703-01			0	Yes	No	" / "	
V608	42" x 10'	1300		1989	801			0	Yes	No	" / "	
V633	42" x 10'	450		1971	02971			0	Yes	No	" / "	Non-Code; Repaired by RAMA in 1999 Model F42
V669	42" x 8'	200		1994	614702-01			0	No	No	" / "	Repaired by Omega Natchie in 2012
V717	42" x 10'	300		1971	607 (?)			3	Yes	No	" / "	2nd Stage Suction Scrubber
V790	42" x 18'	125		0	0						" / "	
V885P	42" x 15'	1240		0	0						" / "	non code
V887P	42" x 9.8'	1237		1969	9240		5617				" / "	Flash Sep
V888P	42" x 9.8'	1237		1969	0						" / "	
V889P	42" x 9.8'	1237		1969	0						" / "	
MV26-59	36" x 10'	1880		1993	K-93-376		2844	3	Yes	No	" / "	

V130	36" x 8'	1200		1970	70052			0	No	No	" / "	glycol contractor - KW International 2005
V135	36" x 8'	1200		1993	0		97	0	Yes	Yes	" / "	Vertical Test
V194	36" x 10'	125		2000	0		289	0	Yes	No	" / "	KW International 2005
V48	36" x 10'	0		0000	0			2	Yes	No	" / "	
V69	36" x 7.5'	125		1994	1834-A		code	2	Yes	No	" / "	vent scrubber
V89	36" x 10'	1000		1977	29318		2090	3	No	No	" / "	
V208	36" x 4'	0		0000	0			0	No	No	" / "	no tag
V209	36" x 10'	1440		0000	0			0			" / "	
V228	36" x 10'	130		1977	77-35932			0			" / "	
V311	36" x 12'	1420		1977	76578		5492	2	Yes	No	" / "	
V252	36" x 15'	230		1973	7351			0	No	No	" / "	
V260P	36" x 15'	1440		1965	4699			0	Yes	No	" / "	repaired by: ROLO MFG 1965
V324	36" x 10'	1440		1977	3-89			3	Yes	Yes	" / "	repaired by: Hahn&Clay 2005 repaired by: NATCO 2000
V342	36" x 7.5'	156		1988	G008-1		82	0	No	No	" / "	
V376	36" x 11'	1000		1991	W-220			0	Yes	No	" / "	
V438	36" x 8'	1440		1985	85-D-6854-OF			0	No	No	" / "	Blowdown Separator
V441	36" x 10'	1200		1952	LTX-279			0	No	No	" / "	repaired by: Wind Production System 1991
V477	36" x 10'	600		1977	T-6589612-01			0	No	No	" / "	vent scrubber; repaired by: Coastline Process 2003
V486	36" x 10'	1440		2010	0310-H2			0	No	No	" / "	
V503	36" x 10'	1440		1989	A12904-01		27	3	No	No	" / "	Repaired by Allen Tank in 1992
V512	36" x 10'	1440		1975	25810		196	0	Yes	No	" / "	Repaired by Sivalls in 1995
V526	36" x 10'	450		1987	59240101			0	No	No	" / "	
V542	36" x 10'	275		1981	81-D-5392-OD			0	Yes	No	" / "	Fuel Gas Scrubber
V567	36" x 10'	1440		1976	101775			2	No	No	" / "	Repaired by Atlas in 1994
V579	36" x 12'	1440		1981	81-D-5392-OB			3	Yes	No	" / "	
V597	36" x 6.5'	1200		1985	1310-01D			2	No	Yes	" / "	
V596	36" x 7'	1200		1985	4183-01E			0	No	No	" / "	Duo Scrubber; Repaired by Latoka Engineering in 1986
V600	36" x 10'	1440		2006	10494			3	No	No	" / "	
V607	36" x 10'	1250		1984	154184			2	No	No	" / "	
V621	36" x 10'	125		1996	86410101			3	No	Yes	" / "	
V650	36" x 10'	1440		0000	8985 02 03			2	No	No	" / "	
V657	36" x 7.6'	250		1988	HL.1V56628.01			0	No	No	" / "	
V660	36" x 10'	150		1990	K-89-784		2345	2	Yes	No	" / "	Surge Tank
V661	36" x 10'	1440		1990	K89-779		2352	3	Yes	No	" / "	
V687	36" x 8'	270		1994	94450-1		13702	0	No	No	" / "	
V688	36" x 8'	700		1994	94450-7		13708	0	No	No	" / "	
V689	36" x 8'	700		1994	94450-4		13705	0	No	No	" / "	
V693	36" x 10'	125		2000	D-00-90		370	3	No	No	" / "	Glycol Separator



<a href="#">V712</a>	36" x 10'	1300		1975	75-145		3405	0	Yes	No	" / "	
<a href="#">V742P</a>	36" x 10'	125		2002	02-22		32290	3	No	No	" / "	Est. weight 1900 lbs.
<a href="#">V759</a>	36" x 10'	125		2007	34351003			0	No	No	" / "	
<a href="#">V754</a>	36" x 10'	125		2009	4103			3	Yes	No	" / "	
<a href="#">V745</a>	36" x 10'	125		2007	06931		36325	2			" / "	
<a href="#">V779</a>	36" x 15'	1000		1983	4-1427-1						" / "	Gas Scrubber
<a href="#">V781</a>	36" x 10'	1440		2011	NIP1789		725	2	No	No	" / "	
<a href="#">V830</a>	36" x 10'	130		1974	74-8926				No	No	" / "	Part of R76
<a href="#">V498</a>	36" x 10'	130		1977	77-A-3608-1			3	No	No	" / "	
<a href="#">V834</a>	36" x 10'	1440		2004	04-201		33710	3	No	Yes	" / "	
<a href="#">V835</a>	36" x 10'	1440		1999	7-1755		27720	3	No	No	" / "	
<a href="#">V837</a>	36" x 7.5'	125		1995	1908-A				No	No	" / "	Vent Scrubber
<a href="#">V867P</a>	36" x 10'	1440		2014	444041		5410	3			" / "	3 Phase Separator
<a href="#">V882P</a>	36" x 8'	250		1969	9239		5616				" / "	
<a href="#">V673</a>	35" x 12'	275		1996	96 567 4524		185	0	Yes	No	" / "	
<a href="#">V131</a>	30" x 9'	1100		1981	2-2152-1-2			0	Yes	No	" / "	ASME#10689-6 Amine Tower
<a href="#">V184P</a>	30" x 8'	1440		1964	6695		3533	0	No	No	" / "	
<a href="#">V193</a>	30" x 8'	275		1985	85-D-6650-04			0	No	No	" / "	vent scrubber / repaired: 1988
<a href="#">V20dl</a>	30" x 12.5'	1440		1990	EL 2A29802-01		NB	3	Yes	No	" / "	Alt. by Universal Fab. 2002
<a href="#">V65</a>	30" x 15'	1440		1968	7101-ECC		code	3	No	Yes	" / "	300 class flanges
<a href="#">V226</a>	30" x 10'	475		1975	5538			0	No	No	" / "	
<a href="#">V249</a>	30" x 10'	125		1996	8215A		188	0		Yes	" / "	vertical water degausser
<a href="#">V296</a>	30" x 10'	100		2001	9748A		306	0	No	No	" / "	vent scrubber
<a href="#">V404</a>	30" x 10'	1440		1980	T7156702-01			3	No	No	" / "	repaired by: Production Facilities 2001
<a href="#">V418</a>	30" x 10'	125		1986	60380			0	No	No	" / "	repaired by: NATCO 1999
<a href="#">V455</a>	30" x 10'	125		2005	1174			2	No	No	" / "	
<a href="#">V458</a>	30" x 10'	125		2005	1204			3	No	No	" / "	
<a href="#">V487</a>	30" x 10'	1480		0000	30446-61			0	No	No	" / "	blow case; repaired by: Universal Equipment 2001
<a href="#">V507</a>	30" x 10'	125		2001	01-61		30993	2	No	No	" / "	Repaired by Tornado Technolitics, Inc. in 2001
<a href="#">V533</a>	30" x 10'	125		2001	01-641			0	No	No	" / "	Glycol Separator on R117
<a href="#">V550</a>	30" x 10'	125		1984	84-1597C		16703	3	No	No	" / "	
<a href="#">V552</a>	30" x 10'	125		1986	59190101			0	No	No	" / "	
<a href="#">V594</a>	30" x 10'	1480		1985	V-85-144-B		212	2	No	No	" / "	30" ID
<a href="#">V595</a>	30" x 8'	1200		1985	21183-C		1183	0	Yes	No	" / "	Outlet Scrub/ Tex Fab Inc. June 1985 SN TF3390 built the shell.
<a href="#">V601</a>	30" x 10'	1440		2006	10493-1			3	No	No	" / "	Head Cut Off
<a href="#">V609</a>	30" x 8'	600		1963	5944		2937	0	No	No	" / "	Repaired by Anderson C. in 1963
<a href="#">V636</a>	30" x 10'	125		0000	1-8514			0	No	No	" / "	
<a href="#">V672</a>	30" x 7.5'	1480		1993	738A			0	No	No	" / "	
<a href="#">V676</a>	30" x 4.75'	125		1984	2962			0	No	No	" / "	

<a href="#">V681</a>	30" x 10'	1480		1997	25041		313	0	No	No	" / "	
<a href="#">V679</a>	30" x 8'	103		1981	563			0	Yes	Yes	" / "	
<a href="#">V692</a>	30" x 7.5'	125		1987	87.106C			3	No	No	" / "	
<a href="#">V709</a>	30" x 10'	125		2006	05-701		35213	3	No	No	" / "	
<a href="#">V713</a>	30" x 10'	0		1996	LS1710			0	No	No	" / "	
<a href="#">V733P</a>	30" x 5'	750		1974	21-130			2	No	No	" / "	
<a href="#">V752</a>	30" x 10'	125		2005	MM9T43101-05		32619	0	No	No	" / "	
<a href="#">V753</a>	30" x 10'	125		2006	7679			0	No	No	" / "	
<a href="#">V755</a>	30" x 10'	125		2008	MM9M34501-02		45871	0	No	No	" / "	
<a href="#">V758</a>	30" x 10'	125		2008	MM9M34501-01		45870	0	No	No	" / "	
<a href="#">V757</a>	30" x 10'	125		2007	MM(T97901-03		39616	0	No	No	" / "	
<a href="#">V769</a>	30" x 6'	125		1986	6802A				No	No	" / "	
<a href="#">V801</a>	30" x 10'	125		2009	08-6958		6099	3	No	No	" / "	
<a href="#">V800</a>	30" x 10'	125		2009	CL09-209		38671	3	No	No	" / "	
<a href="#">V799</a>	30" x 10'	125		2009	CL09-208		38660	3	No	No	" / "	
<a href="#">V840</a>	30" x 10'	1440		2011	W6168		5844	2	Yes	No	" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V841</a>	30" x 10'	1440		2011	W7275		6923		Yes	No	" / "	vertical 2 phase separator with 4" in and out NB registered and 8" clean outs.
<a href="#">V842</a>	30" x 10'	1440		2011	W6153		5842		Yes	No	" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V843</a>	30" x 10'	1440		2011	W6234		5953		Yes	No	" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V844</a>	30" x 10'	1440		2011	W7276		6924				" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V845</a>	30" x 10'	1440		2011	W5152		5795		No		" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V846</a>	30" x 10'	1440		2011	W7273		6926		No		" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V848</a>	30" x 10'	1440		2011	W6657		6847		No		" / "	vertical 2 phase separators with 4" in and out NB registered and 8" clean outs.
<a href="#">V851</a>	30" x 10'	125		2009	CL09-211		38659				" / "	
<a href="#">V850</a>	30" x 10'	125		2009	CL09-207		38672				" / "	
<a href="#">V853</a>	30" x 10'	1440		2011	W6169		5845				" / "	
<a href="#">V854</a>	30" x 10'	1440		2011	W6175		5783				" / "	
<a href="#">V886P</a>	30" x 9.8'	412		1967	7913		4612				" / "	Suction Scrubber
<a href="#">V895P</a>	30" x 8'	144		1969	9209		5597				" / "	

<a href="#">V794</a>	28" x 5'	125		1984	2962		214		No	No	" / "	
<a href="#">V898P</a>	27.5" x 33.5'	180		1999	25349-2						" / "	amine charcoal filter part of PL41P
<a href="#">V576</a>	27.125" x 10'	1440		1977	T-624900-01			3	No	No	" / "	Repaired by Coastline Process in 1992
<a href="#">CB1</a>	26" x 15'	1930		2003	02466-3A		19027	0	No	No	" / "	wt: 9439lbs
<a href="#">CB2</a>	26" x 15'	1930		2003	02466-3B		19028	0	No	No	" / "	wt: 9439lbs
<a href="#">CB3</a>	26" x 15'	1930		2003	02467-3A		19034	0	No	No	" / "	wt: 9439lbs
<a href="#">CB4</a>	26" x 15'	1930		2003	02467-3B		19035	0	No	No	" / "	wt: 9439lbs
<a href="#">CB6</a>	26" x 13.2'	1045		2003	02466-2A		19025	0	No	No	" / "	wt: 5114lbs.
<a href="#">CB7</a>	26" x 13.2'	1045		2003	02467-2B		19033	0	No	No	" / "	wt: 5114lbs.
<a href="#">MV108-221</a>	24" x 7.5'	275		1984	CB116A			0	No	No	" / "	
<a href="#">MV59-202</a>	24" x 7.5'	230		1979	0		code	2	Yes	No	" / "	at 300 degrees
<a href="#">V149</a>	24" x 10'	125		1965	14372			0	Yes	No	" / "	
<a href="#">V181SA</a>	24" x 5'	1440		2004	2066			0	No	No	" / "	vertical blowcase
<a href="#">V58</a>	24" x 7.5'	740		1973	0			2	No	Yes	" / "	vent scrubber
<a href="#">V93</a>	24" x 7.5'	125		1996	94-121		code	0	No	No	" / "	flash separator
<a href="#">V213</a>	24" x 7.5'	125		1989	889019			0		No	" / "	
<a href="#">V227</a>	24" x 10'	1440		0000	749380			0	No	No	" / "	2",3",4"
<a href="#">V233</a>	24" x 10'	1500		1946	41639			0	No	No	" / "	repaired by: Production Facilities 2008
<a href="#">V239</a>	24" x 10'	125		1991	0			0	No	No	" / "	vent scrubber
<a href="#">V338</a>	24" x 7.5'	230		1975	T-4337937-01			0	No	No	" / "	
<a href="#">CB5</a>	24" x 13.2'	1045		2003	02466-2B		19026	0	No	No	" / "	wt: 5114lbs.
<a href="#">V360</a>	24" x 10'	125		1967	67177		1461	0	No	No	" / "	
<a href="#">V377</a>	24" x 10'	1440		1976	76-153			3	No	No	" / "	repaired by: Atlas Products 1993
<a href="#">V452</a>	24" x 7.5'	125		1986	86-43C		19159	0	No	Yes	" / "	flash separator
<a href="#">V476</a>	24" x 10'	1200		1963	0			0	No	No	" / "	repaired by: Facilities 2009
<a href="#">V492</a>	24" x 7'	125		0000	N1-2B21405-01			0	No	No	" / "	flash gas
<a href="#">V506</a>	24" x 7'	125		2005	MM9T33401-02		31027	0	No	No	" / "	flash separator
<a href="#">V551</a>	24" x 10'	1440		1985	85-225		17,148	2	No	No	" / "	
<a href="#">V553</a>	24" x 7.5'	125		1986	59210101			0	No	No	" / "	Tag plate bent
<a href="#">V555</a>	24" x 7.5'	1440		1969	421981			0	No	No	" / "	S/S Vertical Scrubber; Repaired by KW International, Inc. in 2005
<a href="#">V556</a>	24" x 8'	740		1985	85-1			3	Yes	No	" / "	Repaired by K.W. International 2006
<a href="#">V570</a>	24" x 7'	125		2005	MM9T30701-03		30436	3	Yes	No	" / "	
<a href="#">V605</a>	24" x 7.5'	1440		2010	1K4760401			0	No	Yes	" / "	Sand Trap
<a href="#">V610</a>	24" x 7.5'	0		0000	0			0	No	No	" / "	No tag; Dehy
<a href="#">V617</a>	24" x 8'	500		2006	1473			0	Yes	Yes	" / "	
<a href="#">V624</a>	24" x 10'	1440		2007	MM9T90301 05		38821	0	No	No	" / "	
<a href="#">V642</a>	24" x 7.5'	125		2006	4656		472	3	No	Yes	" / "	
<a href="#">V643</a>	24" x 10'	1440		1996	92290		4853	2	No	No	" / "	
<a href="#">V644</a>	24" x 10'	1440		2005	420008			3	No	No	" / "	
<a href="#">V646</a>	24" x 10'	0		0000	0			0	No	No	" / "	

<a href="#">V653</a>	24" x 5'	1440		2004	2067			0	No	No	" / "	
<a href="#">V691</a>	24" x 5'	125		1985	50679			0	No	No	" / "	
<a href="#">V698</a>	24" x 5'	1440		2008	L-08-891		38173	0	No	Yes	" / "	
<a href="#">V718</a>	24" x 7'	125		1997	EL2078903-04		13294	0	No	No	" / "	
<a href="#">V724</a>	24" x 7.5'	125		2000	00436		29904	2	No	Yes	" / "	Repaired by Universal Equipment in 2013
<a href="#">V738</a>	24" x 7.5'	125		1993	93.10200		23687	3	No	No	" / "	Repaired by Production Facilities in 2004
<a href="#">V751</a>	24" x 10'	125		2003	20761			0	No	No	" / "	
<a href="#">V750</a>	24" x 7.5'	0		2005	1001-379			0	No	No	" / "	
<a href="#">V760</a>	24" x 7.5'	125		1980	V7533			0	No	Yes	" / "	Wind Production Systems 1991 SN# W1723
<a href="#">V763</a>	24" x 6'	200		1973	T3200003-01				No	Yes	" / "	
<a href="#">V792</a>	24" x 10'	1000		1980	3963		3310		No	No	" / "	
<a href="#">V798</a>	24" x 10'	1440		2005	1E696.01.02				No	No	" / "	
<a href="#">V812</a>	24" x 7'	1200		2000	3040			2	No	No	" / "	
<a href="#">V816</a>	24" x 8.5'	1440		1947	11285			2	No	No	" / "	Repaired by FLOECO in 2000 SN 3965
<a href="#">V824</a>	24" x 8'	3000		1962	31444-T-1				No	Yes	" / "	Sand Trap Universal 1999 Universal 2008
<a href="#">V827</a>	24" x 10'	1480		2004	9605		3416				" / "	
<a href="#">V829</a>	24" x 10'	1440		1968	CV-1256			3	No	Yes	" / "	
<a href="#">V836</a>	24" x 7.5'	1480		1995	D-98411510		24875		No	No	" / "	Blow Case/ missing head
<a href="#">V866P</a>	24" x 7.5'	1440		2010	IK4760701						" / "	Vertical Sand Trap
<a href="#">V910</a>	24" x 7.6'	1440		1999	99-687			3			" / "	
<a href="#">V908</a>	24" x 7.6'	1440		1997	97-1038		27077				" / "	
<a href="#">V906</a>	24" x 10'	1440		1997	87-200			2			" / "	
<a href="#">V796</a>	22" x 8'	900		1937	93-C				No	No	" / "	Repaired by Union Production Co.
<a href="#">V797</a>	22" x 8'	900		1940	145C				No	No	" / "	
<a href="#">V222</a>	20" x 7.5'	272		1984	16365		10214	2	No	No	" / "	first stage suction scrubber
<a href="#">V332</a>	20" x 10'	1000		2007	2641			3	No	No	" / "	
<a href="#">V378</a>	20" x 7'	1200		1988	EL9E26501-01		13957	3	No	Yes	" / "	repaired by: Production Facilities 2010
<a href="#">V443</a>	20" x 7'	1422		1995	EL-9E03201-04		10732	3	No	No	" / "	
<a href="#">V459</a>	20" x 7.5'	1440		1984	84-1600		16,706	2	No	No	" / "	repaired by: Wind Production System 1990
<a href="#">V466</a>	20" x 8'	1200		1958	H-10915		2938	3	No	No	" / "	repaired by: CF&S 1994
<a href="#">V482</a>	20" x 5.8'	1440		2010	0			0	No	No	" / "	
<a href="#">V495</a>	20" x 5'	230		1981	81-D-5159-OM			0	No	No	" / "	
<a href="#">V558</a>	20" x 10'	1440		1967	18.109			0	No	No	" / "	Oil Gas Separator; Repaired by Doyle's Production
<a href="#">V562</a>	20" x 10'	1480		2002	02-3-59A		42	0	No	No	" / "	HP Suction Scrubber
<a href="#">V561</a>	20" x 10'	1480		2002	02-3-59B		43	0	No	No	" / "	L.P. Suction Scrubber
<a href="#">V560</a>	20" x 7.5'	1422		1981	T9457801-02			0	No	No	" / "	Repaired by National Tank in 1981

<a href="#">V573</a>	20" x 7.5'	1440	1994	94-457	24110	3	No	No	" / "	
<a href="#">V611</a>	20" x 7.5'	0	0000	0		0	No	No	" / "	No tag; Dehy
<a href="#">V615</a>	20" x 7'	0	0000	0		0	No	No	" / "	No tag; deny dry bed
<a href="#">V728</a>	20" x 7.5'	285	1994	606 105-01		2	No	No	" / "	Fuel Gas Scrubber
<a href="#">V782</a>	20" x 8'	500	2011	3A818-010		2			" / "	
<a href="#">V811</a>	20" x 5'	1440	1998	2050		2	No	No	" / "	
<a href="#">V814</a>	20" x 7.5'	1440	1981	S321		2	No	No	" / "	
<a href="#">V817</a>	20" x 6.5'	1440	1999	3936		2	No	No	" / "	
<a href="#">V818</a>	20" x 7.5'	1440	1978	78-662	7272	2	No	No	" / "	
<a href="#">V819</a>	20" x 7.5'	1440	1978	78.8430	7453	2	No	No	" / "	
<a href="#">V820</a>	20" x 7.5'	1440	1961	1488-1		2	No	No	" / "	
<a href="#">V822</a>	20" x 7.5'	1403	1981	S-401		2	No	No	" / "	
<a href="#">V909</a>	20" x 706'	1440	2007	P2354	1354	3			" / "	
<a href="#">V185</a>	18" x 5'	0	1998	9121A	256	0	No	No	" / "	fuel gas scrubber
<a href="#">V141</a>	16" x 5'	1500	0000	0		0	No	No	" / "	
<a href="#">V189</a>	16" x 5'	1000	1977	771003-6		0	No	No	" / "	
<a href="#">V61</a>	16" x 7.5'	0	0000	0		0	Yes	No	" / "	repaired by: CF&S Tank Co 2006
<a href="#">V214</a>	16" x 7.5'	1436	1990	0590-015		0	No	No	" / "	
<a href="#">V215</a>	16" x 7.5'	1436	1989	789005		0	No	No	" / "	
<a href="#">V216</a>	16" x 7.5'	1436	1989	889-018		0	No	No	" / "	
<a href="#">V211</a>	16" x 42'	1440	2004	8046-01	2382	0	No	No	" / "	drip pot
<a href="#">V510</a>	16" x 7'	2000	1997	1106		0	No	No	" / "	Sand Trap
<a href="#">V649</a>	16" x 5'	1435	1984	84 10356	1614101613.01	2	No	No	" / "	
<a href="#">V654</a>	16" x 8'	1440	1985	1310		0	No	Yes	" / "	
<a href="#">V659</a>	16" x 6.1'	1440	1992	3257	0136	0	No	No	" / "	2nd Stage Scrubber
<a href="#">V663</a>	16" x 5'	1440	2005	1169	22	0	No	No	" / "	
<a href="#">V690</a>	16" x 3'	1440	2007	DU7227	36	0	No	No	" / "	Vertical Blow Case
<a href="#">V744</a>	16" x 5'	1435	1977	77679C	6277	2	No		" / "	
<a href="#">V767</a>	16" x 7.5'	1440	2005	4372					" / "	
<a href="#">V743P</a>	16" x 4'	125	1973	23-637			No	No	" / "	Glycol Flash Sep.
<a href="#">V784</a>	16" x 7.5'	1440	2006	2587		2	No	No	" / "	
<a href="#">V785</a>	16" x 7.5'	1440	2006	2454		2	No	No	" / "	
<a href="#">V786</a>	16" x 7.5'	1440	2005	4374		2	No	No	" / "	
<a href="#">V787</a>	16" x 7.5'	1440	2006	2694		2	No	No	" / "	
<a href="#">V788</a>	16" x 7.5'	1435	1976	76 431L	5345	2	No	No	" / "	
<a href="#">V802</a>	16" x 7.5'	1440	2006	2602		2	No	No	" / "	
<a href="#">V803</a>	16" x 16'	1440	2006	2455		2	No	No	" / "	
<a href="#">V804</a>	16" x 7.5'	1440	2005	9-393		2	No	No	" / "	
<a href="#">V805</a>	16" x 7.5'	1440	2005	4188		2	No	No	" / "	
<a href="#">V806</a>	16" x 7.5'	1440	2006	2674		2	No	No	" / "	
<a href="#">V807</a>	16" x 7.5'	1440	2005	9-392		2	No	No	" / "	
<a href="#">V808</a>	16" x 7.5'	1440	2006	2618		2	No	No	" / "	

V809	16" x 7.5'	1440		2005	4260				2	No	No	" / "	
V810	16" x 7.5'	1440		2006	2675				2	No	No	" / "	
V815	16" x 7.5'	1440		2008	2986				2	No	No	" / "	
V833	16" x 5'	1440		2007	V06-633		3020		2	No	Yes	" / "	
V857	16" x 7.6'	1440		2005	4371				2,000			" / "	Non code
V858	16" x 7.6'	1400		2005	4373				2	No	No	" / "	Non code
V859	16" x 7.6'	1440		2005	4193				2	No	No	" / "	missing tag Non code
V860	16" x 7.6'	1440		2005	4136				2	No	No	" / "	Non code
V861	16" x 7.6'	1440		2006	2575					No	No	" / "	Non code
V862	16" x 7.6'	1440		2005	4339				2	No	No	" / "	Non code
V863	16" x 7.6'	1440		2005	4191				2	No	No	" / "	Non code
V864	16" x 7.6'	1440		2006	5014				2	No	No	" / "	Non code Manufacturer- Whitehead Production Equipment
V865P	16" x 7'	740		2007	m9m0230105							" / "	
V678	14" x 5'	275		2003	HS 32006885-08		25311		0	No	No	" / "	
MV62	12" x 5'	0		1969	0				0	No	Yes	" / "	
V195	12" x 4'	150		1992	LW 537		90		0	No	No	" / "	
V686	12" x 4.25'	125		1998	N12E04404-01		14371		0	No	No	" / "	
V297	10.75" x 5'	285		2005	V05-181		1812		0	No	No	" / "	fuel gas scrubber
V911P	10.75" x 5'	285		2006	60006033		739					" / "	
V890P	0	0		0	0							" / "	
V897P	0	0		0	0							" / "	Hot Oil Filter
V907	0	1440		1980	T-7325516-01							" / "	
V893P	0	1440		1953	8715							" / "	

Meter Run													
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info	
MS2	72" x 19'	1480		0000	0			0	No	Yes	" / "	14.3 Out	
MS4	6	1480		0	0500I60				No	Yes	" / "		
MS5	6	0		0	0					Yes	" / "		
MS6	6	0		0	0					Yes	" / "		
MS1P	0	0		2008	0			0	No	Yes	" / "	Sensus 12" AAT-230 meter; Low pressure high volume application; Pressure reducing skid	
MS3	0	1480		0000	06200872			0	No	Yes	" / "		
MS7P	0	1440		0	12108492						" / "		

Inventory													
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info	
T377P	42" x 48'	300		1985	0076							" / "	
V854	30" x 10'	1440		2011	W6175					5783		" / "	

V861	16" x 7.6'	1440		2006	2575				No	No	" / "	Non code
------	------------	------	--	------	------	--	--	--	----	----	-------	----------

Gas Compressors												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
GC10	3.875" x 4.665'	0		2007	363925			0	No	Yes	" / "	Speed 1800
GC11	0	0		0000	0			0	No	Yes	" / "	No Tag, but same as GC10
GC8P	0	0		2007	C1299881/02			0	Yes	No	" / "	wt: 10,928/20MMSCFD/model:BMC-347EF/Reliance400hp/FRG5010S/3550RPM
GC9P	0	0		0000	C1299881/03			0	Yes	No	" / "	wt: 10,928/34MMSCFD/model:BMC-347EF/Reliance400hp/FRG5010S/3550RPM
GC14P	0	0		0000	Engine 4EK03763			0	Yes	Yes	" / "	Engine G3516 Comp Gemini D604; Last recorded hours 69,819 hrs. 10/21/10
GC13P	0	0		0000	Engine 4EK00224			0	Yes	Yes	" / "	Engine 63516 Comp Gemini D-604; Last recorded hours 15899 hrs. 10-7-10
GC12P	0	0		0000	Engine 4EK00224 Comp 50F 738			0	Yes	Yes	" / "	Engine 63516 Comp Gemini D-604; Last recorded hours 16,750 hrs. 10/14/10
GC17P	0	0		0000	0			0	Yes	No	" / "	9390 GSIU Wauk Compressor Package - Rebuilds 0 Hours
GC18P	0	0		2013	C2330495-01						" / "	Model # LMC-311F

Generators												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
G14P	127" x 46'	500		2013	KG13794			0			" / "	Model: Titan 130 142.44 MM BTU/hr Natural Gas 191465lbs 10'7"W x 46'L x 10'9"H
ENG11	96" x 4'	0		0000	399299			0	No	Yes	" / "	No tag Model # 399299
G3	0	0		0000	0			0			" / "	Engine model: F817GU
G4	0	0		0000	210096			0	No	Yes	" / "	50KW Generator
ENG1	0	0		0000	399299			0			" / "	Waukesha 817 model F817GU
ENG2	0	0		0000	0			0			" / "	Waukesha 817 / no tag
ENG3	0" x 9.375' x 8.5'	0		0000	361152			0	No	Yes	" / "	model: P9390GSIU
ENG6	0	0		2005	52434			0	No	No	" / "	
ENG7	0	0		0000	1-4-01			0	No	Yes	" / "	Twin Disc; Model: C107SP4; w/TMC Triplex Pump
ENG8	0	0		0000	205691			0	No	No	" / "	9 3/8 x 8 1/2; Model 67042GU; Spec.: G-24926; Gov. Speed: 1000 LD; Repaired by Oilfield Meter Services in 1990
ENG9	0	0		0000	286434			0	No	No	" / "	Model 7042; RPM: 1000
G8	0	0		0000	4R24223			0	No	No	" / "	54" x 11' skid size; No Tags
ENG10	0	0		0000	0			0	Yes	No	" / "	3306 CAT Engine - No Tag
ENG12P	0	0		0000	C1366 (?)			0	No	Yes	" / "	12 Vat 255
G13	0	1800		0000	89125-3			0	No	No	" / "	Synchronous AC Generator/Detroit Diesel; Skid - 10' L x 44" W; 100 KW; Model # 100sX9E
G18P	0	125 KW		2006	OLY00000LNGT00418						" / "	1600 hours, It is a 145KW with a 8.1L engine Mfg. is CAT

<a href="#">G19P</a>	0	0		2006	OLY00000LNGT00419			480 3ph			" / "	
----------------------	---	---	--	------	-------------------	--	--	---------	--	--	-------	--

Rentals												
Inventory #	Size	WP	Manufacturer	Year	SN	DN	NB	Phase	Manway	Skid	In/Out	Additional Info
<a href="#">LH004-15</a>	60" x 20'	0		1982	T-1337001-01				No	Yes	" / "	Trailer Vin # 624253
<a href="#">LH002-14</a>	48" x 17.5'	0		1987	298573			0		Yes	" / "	Trailer mounted rental unit Trailer Vin # 624277
<a href="#">LH003-15</a>	48" x 17.5'	0		2005	6815						" / "	Trailer Vin # 624278
<a href="#">T218</a>	42" x 25'	1440		2004	04-309		33868	0	No	No	" / "	
<a href="#">R109</a>	36" x 15'	0		1998	1816			0	No	Yes	" / "	
<a href="#">H763P</a>	36" x 10'	1440		2012	1206-01		35	3			" / "	
<a href="#">H764P</a>	36" x 10'	1440		2012	1108-02		26	3			" / "	Trailer Mounted
<a href="#">AR-PRS-001P</a>	4	0		2012	PRX-4R-101			0	No	No	" / "	4" Fig206 pipe w/ rack // 200' of pipe // 20-90's and 2 Tees